

Schedule XLV Form N.134.

P.W.D.

पुनरा - २५१८

MMGSY (GEN)

Maintenance

मामागल कामा विस वि महामागल

DIVISION

SUB DIVISION

सुधामागल - कामा विस

MEASUREMENT BOOK

M.B.No-1391

Five year-Maintenance Bill

Sch. XLV- Form No. 134

Particulars	Details of actual measurement				Contents or area
	No.	L.	B.	D.	
N/W - BGP - Dumka road To					
Makromclik					
Under - m m GSY (Gens)					
Agreement No - 12/16-17					
Agency - Sunil Kumar Mondal					
Age					
Date of start work - 16-6-2016					
Date of completion - 15-6-2017					
Actual completion Date - 12-6-18					
1) Restoration of rain curb.					
do ——— a ——— all Cu					
$10 \times 2 \text{ m} \times 1.20 \text{ m} \times 0.30 \text{ m} = 14.40 \text{ m}^3$					
2) Making up of Berms / shoulder.					
do ——— a ——— all Cu					
$15 \times 5 \text{ m} \times 1.10 \text{ m} = 82.50 \text{ m}^3$					
3) Repair of pot-holes filled with 25 mm.					
do ——— a ——— all Cu					
$4 \times 3 \times 1.20 \text{ m} \times 0.035 \text{ m} = 1.008 \text{ m}^3$					
$2 \times 2 \times 1.0 \text{ m} \times 0.035 \text{ m} = 0.14 \text{ m}^3$					
1.148 m^3					
4) patch repair over pot-holes.					
do ——— a ——— all Cu					
$4 \times 3 \times 1.20 \text{ m} = 14.40 \text{ m}^2$					
$2 \times 2 \times 1.0 \text{ m} = 4.00 \text{ m}^2$					
18.40 m^2					
5) patch repair over bituminous					
do ——— a ——— all Cu					

(Continuation)

