

5th Year Maintenance

60

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of Work - Maintenance of road from Jamuniya Tola Bandh to H/P Mati Histro under MHSY Agency - M/S K. P. Construction					
Agreement No - 57 SBD/2018-19					
Date of start - 22/01/2019					
Aeternal date of completion - 22/10/2019					
① Restoration of Raincots					
4 X 12.00 X 1.20 X 0.30 = 17.28 ft ²					
2 X 8.40 X 1.25 X 0.30 = 6.60 ft ²					
1 X 7.00 X 1.15 X 0.25 = 2.01 ft ²					
3 X 10.00 X 1.20 X 0.30 = 10.80 ft ²					
2 X 9.00 X 1.25 X 0.25 = 5.62 ft ²					
1 X 5.00 X 0.90 X 0.30 = 1.35 ft ²					
2 X 10.50 X 1.20 X 0.25 = 6.30 ft ²					
4 X 8.50 X 1.25 X 0.30 = 12.75 ft ²					
3 X 9.50 X 1.15 X 0.25 = 8.19 ft ²					
1 X 8.50 X 1.20 X 0.30 = 3.06 ft ²					
2 X 9.00 X 1.25 X 0.30 = 6.75 ft ²					
2 X 10.60 X 1.25 X 0.30 = 7.95 ft ²					
1 X 8.00 X 1.20 X 0.25 = 2.40 ft ²					
1 X 7.00 X 1.28 X 0.30 = 2.69 ft ²					
1 X 7.50 X 1.28 X 0.30 = 2.88 ft ²					
2 X 7.00 X 1.20 X 0.25 = 4.20 ft ²					
2 X 7.50 X 1.25 X 0.30 = 5.62 ft ²					
2 X 7.80 X 1.20 X 0.25 = 4.68 ft ²					
					110.53 ft ²

Continuation

Abstract of cost

65

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Restoration of Rain crests					
	Q-VT113P69	(1)	110.53	M ³	
	c R.	365=	2517	R.	40,371=
② Maintenance of earthen shoulder					
	Q-VT113P61	(2)	516.23	M ²	
	c R.	54.37	15	R.	280,67=
③ Maintenance of bituminous surface road.					
(i) Repair to potholes					
	Q-VT113P62	(3)	119.78	M ²	
	c R.	286.92	11	R.	34,367=
(ii) Maintenance of worn road					
	Q-VT113P62	(3)	119.78	M ²	
	c R.	384.81	11	R.	46,093=
(iii) Patch repair:-					
	Q-VT113P62	(3)	119.78	M ²	
	c R.	271=	15	R.	324,78=
④ Maintenance of H.P. culvert					
	Q-VT113P63	(4)	2,148	M ³	
	c R.	1131.64	each	R.	2263=
⑤ White washing on Parapet walls					
	Q-VT113P63	(4)	28.56	M ²	
	c R.	16.80	11	R.	479=
	Continuation -				
	1,84,118=				

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
⑥ cutting of branches of trees					
Q-VTB/P63(5) = 9 Nay					
o R- 107.48/km R- 967=00					
⑦ ceiling of shrubs					
Q-VTB/P63(6) = 19 Nay					
o R- 6.69/km R- 126=00					
⑧ Trimming of grass					
Q-VTB/P63(7) = 1284.00m					
o R- 2.20/m R- 2825=00					
⑨ Painting on concrete surface					

Q-VTB/P63(7) = 100.00ft
 o R- 104=771/m R- 10.49=00

⑩ Maintenance of Road

Marking

Q-VTB/P63(8) = 304.00 Km
 o R- 867=771/m R- 263802=00

⑪ Maintenance of Road

sign

Q-VTB/P64(9) = 1.522 Km
 o R- 1087.63/km R- 1655=00

⑫ Maintenance of 20m

stone

Q-VTB/P64(10) = 1.522 Km
 o R- 749=00/km R- 1140=00
 R- 465.471=00

Continuation 464257=00

Material statement

- Material statement

 - (i) soil - 160.33 m^3
 - (ii) metal - 10.87 m^3
 - (iii) chips - 6.47 m^3
 - (iv) sand - 1.44 m^3
 - (v) bitumen - 0.572 mT

Phosphate	15-10-24	Cat	12/11/24
	2.4		RE.
VICK - 7713 B	D-59		
invoiced by - BIL 5590160563			dated 10-12-24
STY	3.13 M+		
	3.588 M+	T	
used STY	0.572 M+	T	
		STY	
Balancce	0.413 M+	T	

Continuation

continuation
9-558 MT

~~2/24~~
17-12-24
T/F