

Name of work - Ganesh Chaudhary House to  
Dadkhaz Dhansole,  
Schedule XLV-Form No. 134

Biraul

(MMGSX-5C)  
DIVISION

Biraul

SUB-DIVISION

M/N<sub>o</sub>-1056

MEASUREMENT BOOK

Agency - Sri. Ganesh Kumar Tha

# 2nd year Maintenance bill

37

Sch. XLV-Form No. 134

| Sch. XLV-6/11 NO. 154 |                               |                             |    |    |                  |
|-----------------------|-------------------------------|-----------------------------|----|----|------------------|
| Particulars           | Details of actual measurement |                             |    |    | Contents of area |
|                       | No.                           | L.                          | B. | D. |                  |
| N/Of Work             | :                             | Maintenance of Road         |    |    |                  |
| :                     |                               | From Ganesh Chaudhari       |    |    |                  |
|                       |                               | house to Dadokhar dham tole |    |    |                  |
| N/Agency              | :                             | Shri Santosh Kumar          |    |    |                  |
|                       |                               | Jha                         |    |    |                  |
| Agreement No          | :                             | 06-SBD/26-21                |    |    |                  |
| Date of start         | :                             | 10/06/20                    |    |    |                  |
| Act. Comp. Date       | :                             | 14/10/22                    |    |    |                  |

## Measurements

|                                   |     |     |      |   |                      |
|-----------------------------------|-----|-----|------|---|----------------------|
| ① Restoration of raincuts with    |     |     |      |   |                      |
| 300 moorum                        |     |     |      |   |                      |
| 4                                 | 12  | 1.2 | 0.30 | = | 17.28m <sup>3</sup>  |
| 6                                 | 9   | 1.1 | 0.30 | = | 17.82m <sup>3</sup>  |
| 8                                 | 10  | 0.9 | 0.30 | = | 21.60m <sup>3</sup>  |
| 12                                | 6.8 | 0.8 | 0.30 | = | 19.58m <sup>3</sup>  |
| 14                                | 8.2 | 0.6 | 0.30 | = | 20.66m <sup>3</sup>  |
| 2                                 | 14  | 0.9 | 0.30 | = | 7.56m <sup>3</sup>   |
|                                   |     |     |      |   | 104.50m <sup>3</sup> |
| ② Maintenance of Earthen Shoulder |     |     |      |   |                      |
| 8                                 | 2   | 12  | 0.50 | = | 96.00m <sup>2</sup>  |
| 6                                 | 2   | 8.8 | 0.50 | = | 52.80m <sup>2</sup>  |
| 9                                 | 2   | 9.6 | 0.50 | = | 86.40m <sup>2</sup>  |
| 12                                | 2   | 10  | 0.50 | = | 120.00m <sup>2</sup> |
| 10                                | 2   | 16  | 0.50 | = | 160.00m <sup>2</sup> |
| 7                                 | 2   | 9.8 | 0.50 | = | 68.60m <sup>2</sup>  |
|                                   |     |     |      |   | 583.80m <sup>2</sup> |

Continuation



Continuation