

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, समस्तीपुर
e-mail- eerwdsamastipur@gmail.com

पत्रांक 354 अ/३ दिनांक 22.2.2024

प्रेषक:—

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, समस्तीपुर।

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी—सह—सचिव
ग्रामीण कार्य विभाग, बिहार, पटना।

विषय:—

शीर्ष New Maintenance Policy 2018 मद में आवंटन उपलब्ध कराने के संबंध में।

महाशय,

उपर्युक्त विषयक शीर्ष New Maintenance Policy 2018 योजनान्तर्गत निर्मित/
निर्माणाधीन पथों का विहित प्रपत्र में अधियाचना पत्र संलग्न कर भेजा जा रहा है।

अतः अनुरोध है कि संलग्न अधियाचना पत्र के अनुसार आवंटन उपलब्ध कराने की कृपा
की जाय।

अनु०—यथोक्त।

विश्वासभाजन

22/2/24
कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, समस्तीपुर
22.2.24

FROM GFR 19-A**(See Government of India's Division (I) below Rule- 150)****Form of Utilization Certificate upto 22.02.2024****PIU- E.E., R.W.D. Works Division, Samastipur**

S.N.	Name of Scheme	Sanction No.& Date	Amount Received	Particulars
1	Construction of Rural Road under New Maintenance Policy-2018	Secretary cum Empowered Officer BRRDA Bihar Patna vide upto Lt. no.-14 dt.06.02.2024	806190484.00	Certified that out of Rs.806190484.00 received upto 22.02.2024 in favour of Executive Engineer R.W.D. Works Division Samastipur a sum of Rs.787956162.00 has been utilized for the purpose of New Maintenance Policy-2018 Schemes as given in the margine for which it was sanctioned and that the balance of Rs.18234322.00 remaining unutilized at the end of period under report.
			80,61,90,484.00	


2. Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for the which it was sanctioned.

Kind of Checks exercised:-

- i Works have been supervised by Executive/Superintending engineer.
- ii Periodical inspection has been conducted by Executive/Superintending engineer.
- iii Construction materials have been tested.
- iv Measurements have been recorded in the MB's and test check conducted by Assistant Engineer/Executive
- v All other codal formalities have been observed.

3 Physical Progress achieved:-

- i Construction of Road work.
- ii Construction of CD works.


Executive Engineer
Works Division Samastipur
Rural Works Dipartment
Rw.
22.2.24

Requisition Format for scheme Head : MR(3054) Under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

RWD, Works Division : Samastipur													
SI No	Package No	Project ID as Per MIS	Name of Road	Administrative Approval (AA) Letter No & Date		Administrative		Agreement Amount		Agreement No & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)
				5	4	Length (Km)	Amount (In Lakh)	Initial Rectification with Surface Renewal	5 Year Routine Maintenance				
1	RM/SA/SAM/23/0011	32010102195	1.058-T01 to East Tola Baghaumi Hanshankarpur (VR58)	1971 & 31.03.2023	4	1.876	106.700	78.297	20.495	11(MBD)2023-24	10.07.2024	Complete	3149
							106.700	78.29663	20.49505				
Total													23.350

1 Signed Hard Copy and Soft Copy (In Excel) of recorded IRI is enclosed.

2 Up-to-date Physical Progress has been uploaded in MIS


Executive Engineer
RWD (W) Div. Samastipur
22-24



Stereo Analyzer

Name of Customer :	Rajeev Kumar Jha
Name of Work/ Road :	L058-T01 To East Tola Baghat
Lab Job number :	74
Date :	30.12.2023
Section No. :	74

Test Date :	30.12.2023	Road Name :	L058-T01 To East Tola Baghat
Machine No :	396	Road Type :	(R) RURAL ROAD
Start S No :		Side :	
Start E No :		Interval	
Weather :		UV Range :	1858 To 4000 mm/km
Start Location :		Dist Range :	0 To 1.9 * 1000 m
End Location :		Equation :	$Y = 0 * X^2 + 1.136 * X + 132.5$

Print

Generate Report and Graph

Redraw Graph


Map View

File : C:\Users\USER\Desktop\30121420.Xls, Section No. : 74, Eqn : $Y = 0 * X^2 + 1.136 * X + 132.5$

Name of Customer : Rajeev Kumar Jha, Name of Work/ Road : L058-T01 To East Tola Baghat Harishankar, Lab

UV 2858 mm/km

1858



[Signature]
30/12/23
AC

[Signature]
30/12/23
AC

[Signature]
30/12/23
AC

Asst. IT Manager

Name of Road :- L058-T01 To East Tola Baghuni Harishankar

Section no.-74

Date	Time	Section	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI mm/km	CATEGORY	Latitude	Longitude	Event
		No.						ROAD			
30/12/23	14:11:43	74	0.1	270	0	2700	3199	G	25.851326	85.655166	Normal
30/12/23	14:12:32	74	0.1	260	10.1	2600	3086	G	25.852137	85.654483	Normal
30/12/23	14:13:3	74	0.1	250	10.1	2500	2972	G	25.852499	85.653755	Normal
30/12/23	14:13:44	74	0.1	280	10.1	2800	3313	G	25.852764	85.652806	Normal
30/12/23	14:14:11	74	0.1	240	10.1	2400	2858	G	25.854341	85.651762	Curve
30/12/23	14:14:40	74	0.1	250	10.1	2500	2972	G	25.855044	85.651724	Normal
30/12/23	14:15:6	74	0.1	260	10.1	2600	3086	G	25.855975	85.651909	Normal
30/12/23	14:15:49	74	0.1	290	10.1	2900	3426	G	25.856678	85.652055	Curve
30/12/23	14:16:7	74	0.1	270	10.1	2700	3199	G	25.857012	85.651135	Normal
30/12/23	14:16:43	74	0.1	280	10.1	2800	3313	G	25.857248	85.650278	Normal
30/12/23	14:17:10	74	0.1	250	10.1	2500	2972	G	25.857427	85.649194	Normal
30/12/23	14:17:50	74	0.1	260	10.1	2600	3086	G	25.857597	85.64833	Normal
30/12/23	14:18:8	74	0.1	270	10.1	2700	3199	G	25.857853	85.647353	Normal
30/12/23	14:18:47	74	0.1	280	10.1	2800	3313	G	25.858153	85.64648	Normal
30/12/23	14:19:5	74	0.1	270	10.1	2700	3199	G	25.858464	85.645544	Normal
30/12/23	14:19:46	74	0.1	260	10.1	2600	3086	G	25.859053	85.643353	Curve
30/12/23	14:20:7	74	0.1	280	10.1	2800	3313	G	25.859235	85.642722	Normal
30/12/23	14:20:41	74	0.1	260	10.1	2600	3086	G	25.859292	85.642401	Normal
Total =							1.80	Km	Avg. 3148.78		

Executive Engineer
R.W.D.(W) Division,
Samastipur

30/12/23
22

30/12/23
22

30/12/23
22

30/12/23
22

Asst. T. Manager