

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, सासाराम-1

Email ID:-ee.rwd.sasaram1@gmail.com

Mob:- 8986915310

पत्रांक...2893/23 सासाराम/दिनांक...27/11/23

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, सासाराम-1

सेवामें,

नोडल पदाधिकारी (MR 3054)
ग्रामीणकार्यविभाग
पटना, बिहार

विषय :- नई अनुरक्षण नीति-2018MR (3054) योजना के अंतर्गत पथ में कराये गये कार्य के विरुद्ध आवंटन उपलब्ध कराने के संबंध में।

महाशय,

उपरोक्त विषय के संबंध में सूचित करना है कि नई अनुरक्षण नीति-2018 MR (3054) योजना के अंतर्गत पथ में कराये गये कार्य के लिए संवेदक को भुगतान करने हेतु अधियाचना विहित प्रपत्र में भरकर आवश्यक कार्यवाही हेतु समर्पित की जाती है।

अनु० :- यथोक्त।

विश्वासभाजन
(इ० रामचन्द्र पंडित)
कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, सासाराम-1

FORM GFR 19-A

(See Government of India's Decision (I) below Rule-150)

Form of Utilization Certificate up to Dec 2023

Sl.No	Name of Scheme	Sanction No.&Date With Amount (In lace Rs.)	Amount Received (In lace Rs.)	Particulars
1	Construction of Rural roads Under MR	New Maintenance Policy-2018 MR (3054) BRRDA PATNA	12694.80295	Certified that out of Rs. 12694.80295 lakh of grants-in-aid sanctioned during the years 2021-23 Infavor of EE,RWD works division Sasaram-1 sum of Rs 12656.56797 akh has been utilized for the purpose of MR (3054) Schemes as given in the margin for which it was sanctioned and that the balance of Rs. 38.23498 lakh remaining unutilized at the end of the period under report.
	Total:		12694.80295	

2. Certified that I have satisfied my self that the conditions on which the grant-in-aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was utilized for the purpose for which it was sanctioned.


Kind of Checks exercised:-

- Works have been supervised by Executive Engineer/ Superintending Engineer.
- Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- Construction materials have been tested.
- Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/ Executive Engineer.
- All other caudal formalities have been observed.

3. Physical Progress achieved:-

- Construction of Road Works.
- Construction of CD works.


Divisional Accounts Officer
R.W.D, works Division
Sasaram-1


Executive Engineer
R.W.D, works Division
Sasaram-1

OFFICE OF EXECUTIVE ENGINEER, RURAL WORKS DEPARTMENT, WORKS DIVISION, SASARAM-1

Requisition Format for Scheme Head- MR(3054) under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

Name of Works Division:- Sasaram-1

Sl no.	Batch No	Name of Road	Project ID as per M15	Administrative Approval (AA) Letter No & Date	Administrative Approval (AA)		Agreement Amount (in Lakh)		Agreement No & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of RI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Previous Total Allocated Amount (in Lakh)	Up-to-date expenditure as per M15 (in Lakh)	Requisition against work done (in Lakh)	Remarks
					Length (in km)	Amount of (in Lakh)	Initial Rectification with Surface Renewal (in Lakh)	5 Year Routine Maintenance (in Lakh)										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1	RW/RO/SA S/23/001 3	LOJ7-Sasaram Dargason Road 107 to Sakarya (ODR23)	10301002229	1796 20.03.2023	0.67	27.542	17.15369	4.8026	23/09/2022- 022- 23/Sasaram in-1/13	16-Mar-24	0	2457	25	5	0.00000	0.00000	16.90444	
2	RW/RO/SA S/23/002 0	Mokar - Bhainahi Via Indranyan	10301102055	22913 02.05.2023	8.025	600.445	490.14861	72.46257	11/MED/23 24	9-Aug-24	0	2202	25	5	0.00000	0.00000	459.78527	

Divisional Accounts Office
Rural Works Department,
Works Division, Sasaram-1

Executive Engineer
Rural Works Department
Works Division, Sasaram-1


Date	Time	Section	Length	Bumps	Speed	OR	IRI	Category	Latitude	Longitude	Event
		No.	in km	in mm	Rate	mm/km	mm/km	ROAD			
12/12/23	16:27:19	88	0.1	200	10.1	2000	2415	G	24.91469	84.7642	Normal
12/12/23	16:27:28	88	0.1	210	20.2	2100	2515	G	24.91459	84.67	Normal
12/12/23	16:27:41	88	0.1	200	20.2	2000	2415	G	24.91455	84.5757	Normal
12/12/23	16:28:0	88	0.1	200	10.1	2000	2415	G	24.914737	84.4813	Normal
12/12/23	16:28:10	88	0.1	190	20.2	1500	2315	G	24.915025	84.382	Normal
12/12/23	16:28:30	88	0.1	230	10.1	2300	2715	G	24.915125	84.2878	Speed Breaker
12/12/23	16:29:41	88	0.1	200	10.1	2000	2415	G	24.915268	84.249	Normal
Average IRI							2457				

(R) RURAL ROAD		
Good	Average	Poor
<4000	4001-5000	>5001

Scanned with CamScanner

Name of Customer :	Anjali Kumari
Name of Work Road :	Sasaram Dangson Road to Sikariya
Lab Job number :	88
Date :	12-12-2023
Section No. :	88

Test Date :	12-12-2023	Road Name :	Sasaram Dangson Road to Sikariya
Machine No. :	391	Road Type :	(R) RURAL ROAD
Start S No. :	03	Side :	Sasaram
Start E No. :	09	Interval :	
Weather :	Normal	UV Range :	1315 To 4000 mm/km
Start Location :	91463.84 7642	Dist Range :	0 To 0.8 * 1000 m
End Location :	915268.84 249	Equation :	$Y = 0 * X^2 + 1.000 * X + 415.2$



80/12/23
 22/12/23
 EE