

17/10/19
 Soil = 135.13 m³
 Stone mch. D = 3.50 m³
 Stone Screening = 0.81 m³
 10mm Stone chip = 1.82 m³
 Stone dust = 0.037 m³
 SS1 = 39.65 Kg
 RS1 = 25.64 Kg
 VGT10 = 177.175 Kg

155.14
 29.84.24
 = 3.5

4th year ABSTRACT OF COST

N/w - Maint. of Road from Sasaram

Derrigaon Road to Basantpur

Agency - Vijay Kumar Singh

Agg. No - 15/SBD/2019-20

Date of start - 26/08/2019

Actual date of comp. - 20/05/2020

① Restoration of Rainwater

Berms do - do -

Qty vide TMB P. No - (43)

I. No ① 64.774 m³ @ 378.327 24505.20

② Making up of Berms

Shoulder do - do -

Qty vide TMB P. No - (43)

I. No. ② 359.62 m² @ 57.357 20624.20

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L	B	D	
③ Repair of flat holes					
75 mm BM	do				
Qty vide TMB P. No- (43)					
I. No. (3) 3.50m ² @ 11889.75					41614 = ∞
④ Patch repair Over					
Post holes 20mm premix					
Carpet do	do				
Qty vide TMB P. No- (44)					
I. No. (4) 46.625m ² @ 319.70					14906 = ∞
⑤ Patch repair Over					
Bitumit- 20mm premix					
Carpet do	do				
Qty vide TMB P. No- (44)					
I. No. (5) 46.625m ² @ 337.21					15722 = ∞
⑥ Maint. of HPC					
Qty vide TMB P. No- (44)					
I. No. (6/7) 5. No @ 1109.67					5548 = ∞
⑦ Maint. of Road					
Signs do	do				
Qty vide TMB P. No- (44)					
I. No. (7/9) 0.121km @ 1066.50					128 = ∞
⑧ Maint. of 200meter					
km stone do	do				
Qty vide TMB P. No- (44)					
I. No. (8/10) 0.14 km @ 650.87					94 = ∞
⑨ Cutting of branches of tree shrubs					
do	do				
Qty vide TMB P. No- (44)					
I. No. (9/11) 2. No @ 105.39					211 = ∞
⑩ White washing					

Continuation

Scanned with CamScanner