

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
5th year Maintenance Bill					
(Over all 10th R/A Bill)					
N/W → Const of Road From					
To S Path To Chandpur					
Total Under M.M.C.Sy (S.C.)					
N/Agency:- Mittulesh Kumar Singh					
At → Mai Basti Mahadeva Siwan					
District → Siwan (Bihar)					
Ag. No → 36580/2018-19					
D.O.A → 25/07/2018					
D.O.S → 25/07/2018					
D.O.C → (As per Agt) → 24/07/2019					
Rate → @ 10.00% Below (D.O.R)					
Date of Actual completion → 11/04/2019					
Date of Entry :- 12-04-19					
Measurement					
Q. Item No (1) Restoration of Rain					
15.1					
Cuts do do as per E.C.					
5 X 30.0 X $\frac{1.80 + 1.60}{2} \times 0.30 =$					76.50 m ³
2 X 30.0 X 1.80 X 0.30 =					32.40 m ³
1 X 11.75 X 1.80 X 0.30 =					6.34 m ³
1 X 25.0 X 1.60 X $\frac{0.10 + 0.30}{2} =$					8.00 m ³
2 X 20.0 X 1.50 X 0.30 =					18.00 m ³
					141.24 m ³
Q. Item No (2) Makin up of Berms					
15.2					
Shoulder do do as per E.C.					
6 X 30.0 X 1.70 =					306.00 m ³

विभाग, कार्य प्रमण्डल, सिवान-1
सिवान-1, दिनांक... 1/7/24

84

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
5th year maintenance bill					
(Over all 10th km bill)					
Abstract of cost					
Date of Entry :-					
All City vide T.M.B.					
Item No. (1/2) Restoration of Rain					
15.1 Cuts do do as per BQ					
P/ 81 item No. (1/2)					
141.24 m ³					
@ R. 348.46/m ³ R. 49219 = cu					
Item No. (3/2) Making up of Seams					
15.2 shoulder do do as per BQ					
P/ 81-82 item No. (3/2)					
656.13 m ²					
@ R. 51.40/m ² R. 33828 = cu					
Item No. (3/3) Repair of Pot holes					
15.5 Filled with 75 mm WBM					
do do as per BQ					
P/ 82 item No. (3/3)					
152.34 m ²					
@ R. 402.02/m ² R. 61244 = cu					
Item No. (4/4) Patch repair over					
15.3 (1/1) Pot holes with 20 mm					
Premix do do as per BQ					
P/ 82 item No. (4/4)					
152.34 m ²					
@ R. 285.56/m ²					
R. 43502 = cu					
R. 187793 = cu					

Continuation

लक अभियंता का कार्यालय
विभाग, कार्य प्रमण्डल, सिवान-1

30

सिवान-1, दिनांक... 1/12/24

Sch. XLV-Form No. 134					Contents of area
Particulars	Details of actual measurement				
	No.	L.	B.	D.	
			BF-R-187		793 = cu
Item No. (5/5) Patch repairs over					
15.30(i)			Bituminous surface		
			do do as per 4		
P/82 item No. (5/5)					
152.34 m ²					
@ R. 303.99/m ²			R. 46		310 = cu
Item No. (6/7) maint of HPL					
15.70(i)			do do as per 4		
P/83 item No. (6/7)					
2 Nos @ R. 1098.11/each				R.	2196 = cu
Item No. (7/9) maint of Road					
15.9			Sign do do as per 5		
P/83 item No. (7/9)					
0.23 KM @ R. 1054.98/KM				R.	245 = cu
Item No. (8/10) maint of 200m x 8m					
15.11			Stone do do as per 1		
P/83 item No. (8/10)					
0.37 KM @ R. 567.15/KM				R.	211 = cu
Item No. (9/11) Cutting of branches					
15.12(i)			of tree do do as per 1		
P/83 item No. (9/11)					
3 Nos @ R. 102.49/each				R.	307 = cu
Item No. (10/11) Cutting of Shrubs					
15.12(ii)			do do as per 4		
P/83 item No. (10/11)					
73 Nos					
@ R. 6.29/each				R.	82 = cu
Rs - 237144 = cu					

Continuation

Details of actual measurement				
No.	Ft.	B.	D.	of slab
SI No. 237/144/141				
Removal of parapet walls				
do do as per E4				
P/E 3 item no (11/12)				
33.0 m ²				
@ R 210/m ²				
R/- 69200				
Removal of white washing				
15.13				
of Parapet walls do -				
do as per E4				
P/E 3 item no (12/12)				
41.76 m ²				
@ R 15.51/m ²				
R/- 64800				

R/- 237861 = 00				
Less @ 10.0% as per				
Agt @ R/- 23787 = 00				
R/- 214074 = 00				
Urmal				
12/10/24				
A/count				
Barbana				
No.	Ft.	B.	D.	of slab
Details of actual measurement				
Control				