

381/20-21

ਸੀਟਿੰਗ ਪ੍ਰਦਰਸ਼ਨੀ ਦੇ ਪ੍ਰਦਰਸ਼ਨੀ
(ਅੰਤਰਰਾਸ਼ਟਰੀ)

Schedule XLV-Form No. 134

Vinodhna Singh

ਬਰਿਕ

DIVISION

ਮਾਨਵਰ

ਸੀਟਿੰਗ

SUB-DIVISION

Measurement Book

ਸੀਟਿੰਗ ਪ੍ਰਦਰਸ਼ਨੀ, 1970-71

4th Year Maintenance

18

Sch. XLV-Form No. 134

Sch. XLV-Form No. 15					Contents of area
Particulars	Details of actual measurement				
	No.	L.	B.	D.	
Name of work - Maintenance of road from Mathiya Purav Tola to Bixta Mathiya Ghri Tola under MHO/SY (Gen)					
Agency - Virindra Singh					
Agreement No - 22SBD/2019-20					
Date of Start - 27/08/2019					
Actual date of Completion - 25/05/2020					
4th Year Maintenance? 26/05/2023 to period 25/05/2024					
① Maintenance of earthen shoulder					

1	X	9.00	X	1.15	=	10.35 ^L
2	X	6.00	X	1.25	=	15.00 ^L
1	X	4.00	X	0.80	=	3.20 ^L
1	X	6.50	X	1.10	=	7.15 ^L
2	X	7.00	X	1.15	=	16.10 ^L
1	X	10.25	X	1.20	=	12.30 ^L
1	X	6.00	X	1.20	=	7.68 ^L
1	X	4.60	X	0.90	=	4.14 ^L
1	X	8.25	X	1.25	=	10.31 ^L
1	X	6.10	X	1.20	=	7.32 ^L
2	X	11.00	X	1.25	=	27.50 ^L
1	X	8.50	X	1.20	=	10.20 ^L
1	X	6.60	X	1.25	=	8.25 ^L
Continuation						139.50 ^L

Abstract of cost

21

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Restoration of Rain cuts					
Q-VTMBP19② = 57.47H ³					
c R-380.58/H ³ - R-21872=0					
② Maintenance of earthen shoulder					
Q-VTMBP18① = 139.50H ²					
c R-58.60/H ² - R-8175=0					
③ Maintenance of bituminous surface road					
(i) Repair to Pot holes					
Q-VTMBP20② = 29.01H ²					
c R-339.19/H ² - R-9840=0					
(ii) Maintenance of WBM road					
Q-VTMBP20③ = 29.01H ²					
c R-518.65/H ² - R-15046=0					
(iii) Patch repair:-					
Q-VTMBP20④ = 29.01H ²					
c R-322.35/H ² - R-9351=0					
④ cutting of branches of trees					
Q-VTMBP19③ = 4 Nos					
c R-106=52/each R-426=0					
⑤ cutting of shrubs					
Q-VTMBP19⑤ = 8 Nos					
c R-6.54/each R-52=0					

Continuation

64762=0

Scanned by CamScanner