

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1. Repair work - Horizontal Tola NH-28 Tangar Ram Ke ghar to verpke Saman Saman Dora Horizontal tola					
2. Agency Vijay kr Ranshan, Sudhaka Madhopur, Mahapur					
3. Aggr. 100 g/LV/SPD-08/12-13					
4. Date of start 03-07-2018					
5. Actual time of complete 25-4-2019					
10. Restoring surface					126.4 m ²
37x 2.5x 0.90 x 0.9 =					125.6
37x 2.75x 0.90 x 0.6 =					54.95
					180.55
2. Maintenance of earthen shoulder					
37x 3.0x 0.90 =					99.9 m ²
3. Maintaining surface					
8 x 3.75 =					30.0 m ²
10 x 3.75 =					37.5 m ²
15 x 2.50 =					37.5 m ²
12 x 2.2 =					26.4 m ²
4 x 3 2.0 =					8.6 m ²
					140.0 m ²
4. Patch repair -					
Area hole 1 m ² (3) =					140.0 m ²

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1. Restoration of saw cut					
Trav. P(73) -					181.06m ³
CB 362 = 51/m ³ -					15,546 = 0
② mending earthen shoulder					
Trav. P(73) -					399.0m ²
CB 54 = 63/m ² -					54575 = 0
③ Repair of pot holes					
Trav. P(73) -					140.0m ²
CB 265 = 207/m ² -					37,212 = 0
④ Patch repair -					
Trav. P(73) -					140.0m ²
CB 246 = 63/m ² -					34,528 = 0

⑤ 1/4 mending of slab top surface					
Trav. P(74) -					8.02
CB 2263 = 53/each -					18,108 = 0
⑥ 1/9 mending of 20cm bed layer					
Trav. P(74) -					2.0 km ²
CB 729 = 207/km ² -					1460 = 0
					2,11,429 = 0
less 10% As Agmt					21,143 = 0
					1,90,286 = 0

mending					
⑦ 1m ² -					281.0m ³
⑧ Stone Agmt -					10.88m ³
⑨ 1m ² -					0.672 m ³
⑩ 1m ² -					21.05/24
21.05/24					21.05/2024