

4th year maintenance

Bill

83

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Content of area
	No.	L.	B.	D.	
Name of work: Construction of Road from Dumari chattri bridge to Dunda village					
Name of Agency: Shafat Prasad Construction Pvt. Ltd					
At: 165 AP Colony					
Dist: Gaya, Bihar					
Agreement No- 104/NABARD/SBD/2017-2018					
Supplementary Agreement No- 29/NABARD/SBD/2018-19					
Date of Commencement- 04.02.17					

Date of Actual Completion of Part A- 17.05.2018

① Restoration of Rain cuts / Berms with Soil-dado

28	25.0	1.13	0.30	= 237.30 m ³
25	15.0	1.13	0.30	= 127.125 m ³
20	10.0	1.13	0.30	= 67.8 m ³
35	8.0	1.13	0.30	= 94.92 m ³
65	12.0	1.13	0.30	= 264.42 m ³
15	18.0	1.13	0.30	= 91.53 m ³
19	15.0	1.13	0.30	= 96.615 m ³
12	10.0	1.00	0.30	= 36.0 m ³

Continuation

Total = 1015.71 m³

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(2) Making up Berms/ Shoulder do do					
15 X 30'0" X 1.13 m					= 508.50 m ²
25 X 30'0" X 1.13 m					= 847.50 m ²
28 X 30'0" X 1.13 m					= 949.20 m ²
35 X 30'0" X 1.13 m					= 1186.50 m ²
45 X 30'0" X 1.13 m					= 1525.50 m ²
55 X 30'0" X 1.13 m					= 847.50 m² ^{169.50 m}
10 X 30'0" X 1.13 m					= 339.0 m ²
5 X 30'0" X 1.13 m					= 169.50 m ²
					Total = 5695.0 m ²

(3) Repair of Pot

holes filled with

25 X 1.50 X 1.00 m	=	37.50 m ²
15 X 2.50 X 1.25	=	46.875 m ²
18 X 1.75 X 1.20 m	=	37.80 m ²
28 28 X 2.00 X 1.10 m	=	61.60 m ²
25 X 1.60 X 1.25 m	=	46.00 m ²
29 X 2.40 X 1.20 m	=	48.72 m ²
24 X 2.60 X 1.10 m	=	42.24 m ²
15 X 1.20 X 0.90	=	16.20 m ²
26 X 1.10 X 0.80	=	22.88 m ²
30 X 1.80 X 1.30	=	70.20 m ²
38 X 1.10 X 0.80	=	33.44 m ²
22 X 1.40 X 1.20	=	36.96 m ²
34 X 1.60 X 1.10	=	59.84 m ²
42 X 1.40 X 1.20	=	70.56 m ²

Continuation

C.O 2 = 630.81 Sup

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	25	1.80	1.50		= 67.50 m ²
	21	1.60	1.20		= 40.32 m ²
	18	2.0	1.80		= 64.80 m ²
	19	1.80	1.10		= 37.62 m ²
	24	1.90	1.25		= 57.00 m ²
	28	1.60	1.30		= 58.24 m ²
	29	1.80	1.60		= 83.52 m ²
	33	1.50	1.25		= 61.875 m ²
	28	1.80	1.60		= 80.64 m ²
	Total =				1182.33 m ²

(4) Patch rep air by

MSS - do - do

25	1.50	1.00		= 37.50 m ²
15	2.50	1.25		= 46.875 m ²
18	1.75	1.20		= 37.80 m ²
28	2.0	1.10		= 61.60 m ²
25	1.60	1.15		= 46.00 m ²
29	1.40	1.20		= 48.72 m ²
24	1.60	1.10		= 42.24 m ²
15	1.20	0.90		= 16.20 m ²
26	1.10	0.80		= 22.88 m ²
30	1.80	1.30		= 70.20 m ²
38	1.10	0.80		= 33.44 m ²
22	1.40	1.20		= 36.96 m ²
34	1.60	1.10		= 59.84 m ²
42	1.40	1.20		= 70.56 m ²

Continuation

C.O. = 630.815 m²

Sch. XLV-Form No. 134 $8/F = 630.815m$

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	25x	1.80x	1.90		= 67.50m ²
	21x	1.60x	1.20		= 40.32m ²
	18x	2.00x	1.80		= 64.80m ²
	19x	1.80x	1.10		= 37.62m ²
	24x	1.90x	1.25		= 57.00m ²
	28x	1.60x	1.30		= 58.24m ²
	29x	1.80x	1.60		= 83.52m ²
	33x	1.50x	1.25		= 61.875m ²
	28x	1.80x	1.60		= 80.64m ²
	Total =				1182.33m ²

(5) patch repair by
MS bitumen

surface
2nd coat

Qty measured same
as above item

rev - (4) = 1182.33m²

(6) maintenance of
Huro pipe culvert

1x 14.02m — 14.02m

(7) maintenance of
Rec culvert

1x 0.72m — 0.72m

(8) record of road width

1x 1.92m — 1.92m

Continuation

Continuation

ABSTRACT OF COST

88

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Restoration of each cut - etc.					
1015.71 m ³ styms page ⁽⁸³⁾ ₀₁					
@ ₹ 351.06/m ³ — ₹ 356575=0					
② Make up Bens/ Shred ends					
5695.20 m ² styms page ⁽⁸⁴⁾ ₂					
@ ₹ 27.30/m ² — ₹ 155429=					
③ Repair of Ref Rates Lotted with 75 mm					
1182.33 m ² styms page ⁽⁸⁵⁾ ₃					
1182.33 @ ₹ 212.74/m ² ₹ 251529=0					
④ Patch repair by mss double coat					
1182.33 m ² styms page ⁽⁸⁶⁾ ₄					
@ ₹ 83.26/m ² — ₹ 99032=0					
⑤ Patch repair by mss 2 nd coat					
1182.33 m ² styms page ⁽⁸⁶⁾ ₅					
@ ₹ 75.86/m ² — ₹ 89691=0					
⑥ Repair of Hume pipe culvert etc					

Continuation

Continuation

[illegible]

Continuation