

# 5th Year Maintenance

Sch. XLV-Form No.134

14

| Particulars                           | Details of actual measurement |    |    |    | Contents of area |
|---------------------------------------|-------------------------------|----|----|----|------------------|
|                                       | No.                           | L. | B. | D. |                  |
| Name of work- Maintenance of          |                               |    |    |    |                  |
| road from Hasi Prinsy road            |                               |    |    |    |                  |
| Harnaraina to Naya Tola               |                               |    |    |    |                  |
| Harnaraina, via Prathmik              |                               |    |    |    |                  |
| Vidyalaya Harnaraina (Munsy)          |                               |    |    |    |                  |
| Agency- M/S Trakur Constn             |                               |    |    |    |                  |
| Agreement No- 19 SBD/2015-16          |                               |    |    |    |                  |
| Date of start- 19/04/2015             |                               |    |    |    |                  |
| Date of completion- 03/04/2016        |                               |    |    |    |                  |
| Actual date of completion- 20/03/2017 |                               |    |    |    |                  |
| 5th Year Maintenance 21/03/2021       |                               |    |    |    |                  |
| Period 20/03/2022 to 20/03/2022       |                               |    |    |    |                  |
| ① Restoration of Rainwater            |                               |    |    |    |                  |

|     |       |        |          |                     |
|-----|-------|--------|----------|---------------------|
| 1 X | 6.10  | X 1.20 | X 0.30 = | 2.20m <sup>3</sup>  |
| 2 X | 8.40  | X 1.25 | X 0.25 = | 5.00m <sup>3</sup>  |
| 2 Y | 7.40  | X 1.15 | X 0.25 = | 4.02m <sup>3</sup>  |
| 2 Y | 10.40 | X 1.25 | X 0.30 = | 7.50m <sup>3</sup>  |
| 2 X | 11.40 | X 1.28 | X 0.30 = | 8.45m <sup>3</sup>  |
| 2 X | 9.50  | X 1.28 | X 0.30 = | 7.30m <sup>3</sup>  |
| 2 X | 7.50  | X 1.20 | X 0.30 = | 5.40m <sup>3</sup>  |
| 2 X | 8.50  | X 1.25 | X 0.30 = | 6.37m <sup>3</sup>  |
| 3 Y | 10.50 | X 1.25 | X 0.30 = | 11.81m <sup>3</sup> |
| 2 X | 8.40  | X 1.25 | X 0.30 = | 6.00m <sup>3</sup>  |
| 2 X | 9.20  | X 1.10 | X 0.25 = | 5.06m <sup>3</sup>  |
| 3 Y | 7.50  | X 1.25 | X 0.25 = | 7.03m <sup>3</sup>  |
| 1 X | 6.40  | X 1.25 | X 0.30 = | 2.25m <sup>3</sup>  |
| 3 X | 10.40 | X 1.25 | X 0.30 = | 11.25m <sup>3</sup> |

Continuation

12

89.64m<sup>3</sup>

# Abstract of cost

Sch. XLV-Form No.134 18

| Particulars                              | Details of actual measurement |    |    |    | Contents of area |
|------------------------------------------|-------------------------------|----|----|----|------------------|
|                                          | No.                           | L. | B. | D. |                  |
| ① Restoration of Rain cuts               |                               |    |    |    |                  |
| Q-VTMBP14(1) = 89.64m <sup>3</sup>       |                               |    |    |    |                  |
| P15(3) = 62.23m <sup>3</sup>             |                               |    |    |    |                  |
| 151.87m <sup>3</sup>                     |                               |    |    |    |                  |
| e R 310.20/m <sup>3</sup> - R - 47,110/- |                               |    |    |    |                  |
| ② Maintenance of earthen Shoulder        |                               |    |    |    |                  |
| Q-VTMBP15(2) = 239.94m <sup>3</sup>      |                               |    |    |    |                  |
| P16(5) = 103.59m <sup>3</sup>            |                               |    |    |    |                  |
| P17(6) = 289.16m <sup>3</sup>            |                               |    |    |    |                  |
| 632.69m <sup>3</sup>                     |                               |    |    |    |                  |
| e R 48 = 46/m <sup>3</sup> R 30976/-     |                               |    |    |    |                  |
| ③ Maintenance of bituminous surface road |                               |    |    |    |                  |
| (i) Repair to pot holes                  |                               |    |    |    |                  |
| Q-VTMBP16(4) = 53.32m <sup>3</sup>       |                               |    |    |    |                  |
| e R 341 = 17/m <sup>3</sup> R - 18191/-  |                               |    |    |    |                  |
| (ii) Patch repair:-                      |                               |    |    |    |                  |
| Q-VTMBP16(4) = 53.32m <sup>3</sup>       |                               |    |    |    |                  |
| e R 324.89/m <sup>3</sup> R - 17323/-    |                               |    |    |    |                  |
| ④ Maintenance of road work               |                               |    |    |    |                  |
| Sign - sign                              |                               |    |    |    |                  |
| Q-VTMBP17(1) = 0.20Km                    |                               |    |    |    |                  |
| e R 582.47/km R 175/-                    |                               |    |    |    |                  |
| R 1,13,775/-                             |                               |    |    |    |                  |

Continuation

