

સાધારણ - જીલ્લો કે જિલ્લાધિકારી

Schedule XLV-Form: No. 134

MMGSY (Gen)

જિલ્લા સ્તર

DIVISION

(MMGSY)

SUB-DIVISION

કચ્છ

MEASUREMENT BOOK

3727

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>ABSTRACT OF COST</u>					
1. Restoration of main					
Cut with Sudon morum					
Quantity vide Page-(28)					
Of T.M.B: 5111/3					
@RS. 404.06/m ² RS. 20607-					
2. Maintenance of earthen					
Sh. Sides (filling with					
fresh selected soil). Quantity					
Vide Page-(28) of T.M.B-					
282 M ² @RS. 60.28/m ² RS. 169992-					
3. Maintenance of Bitumen					
road Seal Surface					
Quantity vide Page-(28).					
22.50 M ² @RS. 493.18/m ² RS. 110972-					
4. Maintenance H.P.C. vide					
Page-(28)- 1 No.					
@RS. 1166.58 each RS. 11672-					
5. Maintenance of 20cm					
and km stone vide Page-(28)					
0-50KM @RS. 748.22/km RS. 374200					
RS. 50,2442-					
Add 2-1. Labour less and 121 RS. 653220					
Gr. 5-T RS. 56,7762-					
less 8.77 - 1. below RS. 49792-					
RS. 51,7972-					
25/11/24 Shankar 25/11/24 Ch					
J.E. 06/02/24					

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>Material Statement</u>					
1. E/W 1579.20 M ²					
@ RS. 34.81/M ²					RS.
2. Bitumen (5-90) - 0.043 M.T.					
3. chips - 0.04 M ³					
@ RS. 604.91/M ³					RS.
<u>25/1/24</u> J.R.	<u>25/1/24</u> Shakar RZ				
Bitumen available on site					
Nide Rate (48) of M.B. No. (B107)					3434.85
					3.43485 M.T.
Bitumen Consumed at site @ 0.043 M.T.					
Bitumen Balance					3.39185 M.T.
<u>25/1/24</u> J.E	<u>25/1/24</u> Shakar RZ				