

1st year Maintenance Bill

72

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of Work:- Const of Road from					
Sinjodpur to 1038 under					
consy in Biharsahay Block					
Agency:- Rajesh Kumar					
Agreement:- SBD 39/2019-20					
Date of start:- 06-08-2019					
Date of completion:- 05-08-2020					
Actual date of completion:- 30-11-2021					
Date of entry:-					

ABSTRACT OF COST

① Restoration of Rain cuts

77.787 m ³	VTMB-3070, P-6	
@ Rs 380.52/m ³		Rs 29599.00

② Maintenance of earthen shoulder

430.32 m ²	VTMB-3070, P-6	
@ Rs 57.31/m ²		Rs 24662.00

③ Patch repair over B.T Surface

34.56 m ²	VTMB-3070, P-7	
@ Rs 301.85/m ²		Rs 10425.00

④ Maintenance of H.P Culvert

9.00 No	VTMB-3070, P-7	
---------	----------------	--

Continuation

Particulars	Details of actual measurement			Contents of area
	No.	L.	B.	
① Maintenance of slab culvert				
Do	Do	Do	Do	Rs 4468.00
1.00 No			VTMB-3070, P-7	
			@ Rs 2309.04/No	Rs 2309.00
② Maintenance of Road Signs				
Do	Do	Do	Do	Rs
0.20 km			VTMB-3070, P-7	
			@ Rs 1074.51/km	Rs 215.00
③ Maintenance of 200m & km Stones				
Do	Do	Do	Do	Rs
0.24 km			VTMB-3070, P-7	
			@ Rs 651.45/km	Rs 156.00
④ Cutting of branches of trees				
Do	Do	Do	Do	Rs
4.00 No			VTMB-3070, P-7	
			@ Rs 106.52/No	Rs 426.00
⑤ White washing of parapet walls				
Do	Do	Do	Do	Rs
82.56 m ²			VTMB-3070, P-8	
			@ Rs 16.27/m ²	Rs 1343.00
				Rs 73,603.00
less 1.3% Below				Rs 964.00
				Rs 72,639.00
Answer 19/11/23 56				

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
2nd Year Maintenance					
Named work - Maintenance of Road					
from Sanjodpur to 1038					
with M.M.P. 10					
Biharshahd Block					
Agency - Rajesh Kumar					
Agreement No. 33D-29/2019-20					
date of start					06/8/2019
date of completion					05/08/20
actual date of completion					30/11/21
① Restoration of pavement with 30% M.M.P.					
etc in all compl					

18x	3.0M	1.0M	0.3M	35.64M ²
22x	6.0M	0.90M	0.3M	
12x	5.0M	0.85M	0.3M	28.05M ²
			total	101.49M ²
			limit	93.20M ²
② Maintenance earthen shoulder in all				
20x	3.0M	1.0M		140.0M ²
19x	6.0M	0.90M		133.90M ²
16x	5.0M	0.85M		68.0M ²
14x	6.0M	0.90M		75.60M ²
13x	8.0M	0.75M		78.0M ²
5x	4.0M	1.0M		20.0M ²
			total	534.90M ²

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	ABSTRACT OF COST				
①	Restoration of Raincur				
	width TMS. PSC 25' 24" ①				
Qty: 2	97.20 MS	380.52/MS			36987 = 10
②	Maintained earth structure				
	width TMS. PSC 25' 24" ②				
Qty: 2	534.90 M ²	57.31 M			30655 = 10
③	patch separation over				
	between square				
	width TMS. PSC 26' 24" ③				
Qty: 2	24.0 M ²	301.65 M ²			22322 = 10
④	Maintained Hip corner				
	width TMS. PSC 26' 24" ④				
⑤	Maintenance of glass corner				
	width TMS. PSC 26' 24" ⑤				
Qty: 2	01 MS	2309.04/MS			2309 = 10
⑥	Maintained Road 81cm				
	width TMS. PSC 26' 24" ⑥				
Qty: 2	0.24 MS	1074.51/M			258 = 10
⑦	Maintained 210M & 4M 50cm				
	width TMS. PSC 26' 24" ⑦				
Qty: 2	0.30 M	651.245/M			195 = 10
⑧	Curb & Base of tree				
	width TMS. PSC 26' 24" ⑧				
Qty: 2	04 MS	106.52/MS			426 = 10
⑨	Wheel wash & PSC 26' 24" ⑨				
	width TMS. PSC 26' 24" ⑨				
Continuation					
Qty: 2	84.04 M ²	16.22 M ²			1367 = 10
					98987 = 10

Continuation