

work name - Dihenpur peeki sader (toh)
to north tola

MB No-556

(14)

Schedule XIV-Form No. 134

Subhash Ranjaya

DIVISION

SUB-DIVISION

Block - Marhaura

556

Measurement Book

Subash Ranjaya

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>First to Maintenance</u>					
<u>Name of Work - Maintenance work</u>					
<u>Olakombur Pakki Sadak (Gobainya)</u>					
<u>Se North To La Tale.</u>					
<u>Name of Agency - Sri Subhash Ranjan</u>					
<u>Agg. No. 77/MYGSY/19-20.</u>					
<u>Date of Commencement - 06.03.19</u>					
<u>Date of Completion - 05.03.20</u>					
<u>Period - 16.04.21 to 15.04.22</u>					
<u>Date of Actual work - 15.04.21</u>					
<u>Date of Entry - 16.04.22.</u>					
<u>Record Entry.</u>					

<u>S.No.1. Restoration of Road</u>					
<u>Cuts etc cut up</u>					
	2x	18.20x	1.20x	0.90	= 35.00
	1x	22.30x	1.05x	1.00	= 23.415
	2x	18.35x	1.00x	0.90	= 33.03
					<u>91.445</u>
					3
					(4- 89.854
<u>S.No.02 - Making up of Berms</u>					
<u>Shoulders, stripping etc.</u>					
	1x2x	30x	1.15		= 69.00
	2x2x	30x	1.20		= 144.00
	1x2x	30x	1.02		= 61.20
					<u>274.20</u>
					11

	AG Stock of Cost -	
J. No. 1.	Restoration of Rainwater Beams with soft set c.	
	Vide P. No. 46 in T. 4. B	
89.85	$\times \frac{3}{4} R - 365 = 25 \times \frac{3}{4} R$	328/8 = 0
J. No. 02 -	Making up of Beams shoulder etc with c.	
	Vide P. No. 46 in T. 4. D	
274.20	$\times \frac{3}{4} R - 54 = 16 \times \frac{3}{4} R$	1485/1 = 0
J. No. 03	Patch repair Over bituminous surface	
	Vide P. No. 47 in T. 4. D	
23.10	$\times \frac{3}{4} R - 320 = 46 \times \frac{3}{4} R$	7403 = 0
		R = 55072/ =

Continuation

[illegible]