

2017 Year Maintenance Bill

21

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>Abstract of cost</u>					
① Restoration of Raincuts.					
40.28sq <sup>2</sup> (By vide P.No. 18					
@ 404.06/- Rq: 16,275:00					
② Making up of kerms					
Shoulder.					
274.90sq <sup>2</sup> (By vide P.No. 18					
@ 60.28/- Rq: 13,557:00					
③ Patch repairs over bituminous					
surface with same material.					

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
					BF : 42,60 S : 00
less for below					18.98 r.g. : 7897 : 00
					TO : 33,708 : 00
Musanto					
11/5/24					
JE					11.05.24
					AE