

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>4th Year Maintenance</u>					
N/W-	SH Se Maricha	PMGSY Path			
	Yadan Tola & Utkarmit				
	Vidhalay Isarapur Kinara				
	Sadak Tak				
Agency-	Sai Kamal Sri Sankar Singh				
Agreement-	26 SBD / 2019-2020				
Date of start-	06/08/2020				
Actual Date of completion-	20/08/2020				
<u>Measurement</u>					
(15.1)	Restoration of Raincut				
	Bennis do do all complete job				
	2x	15.04	1.10	0.30	9.60
	2x	20.04	1.10	0.30	13.20
	1x	30.04	1.10	0.30	9.90
	1x	25	1.0	0.30	7.50
	1x	23	1.0	0.30	6.90
	2x	27.04	1.10	0.30	17.82
	2x	25	1.10	0.30	16.50
	1x	17.5	1.10	0.30	5.784 ³
					87.204 ³
					Limit = 87.084 ³

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(2/15.2) Making up Basins/Shoulders					
Shipping of excess soil etc.					
	1	30.04	1.0	=	30.04 ²
	2	25	0.90	=	45.04 ²
	2	28.04	1.0	=	56.04 ²
	2	30.04	1.0	=	60.04 ²
	2	18	1.0	=	36.04 ²
	2	20.04	1.0	=	40.04 ²
	2	12.50	1.0	=	25.50 ²
					<u>292.50²</u>

(3/15.5) Repair of Pot holes filled
with 75 mm NBM & 1-2 do do
all complete job.

	5	1.5	0.80	=	6.04 ²
	10	2.5	0.75	=	18.75
	6	1.80	1.0	=	10.80
	5	2.0	1.0	=	10.0
	7	1.50	0.60	=	6.30
	4	1.2	1.0	=	4.80
	3	1.59	0.90	=	4.29
					<u>60.94²</u>

(4/15.3) Patch Repair over Pot holes
do do all complete job.
Date of work P. No. (48)
Item no (3/15.5) - 60.94²

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<p>7/15-7(ii) Patch Repair over bituminous surface do-do all complete job</p> <p>Qty V.M.B P.No - (49)</p> <p>Item No - (2/15-8) 60.94 m²</p>					
<p>7/15-7(i) Maintenance of G.D work do-do all complete job</p> <p>1 x 1-0 m = 1.0 m</p>					
<p>9/15-9 Maintenance of Road Signs do-do all complete job</p> <p>5 x 30-04 = 150.04</p> <p>1 x 10-04 = 10.04</p> <p>160.4</p> <p>⇒ 0.160 km</p>					
<p>10/15-11 Maintenance of 200m p.km stones etc</p> <p>6 x 30-04 = 180.04</p> <p>1 x 10-04 = 10.04</p> <p>190.04</p> <p>⇒ 0.190 km</p>					
<p>11/15-12(i) Cutting of branches of trees and shrubs etc</p> <p>1 x 2-0 m = 2.0 m</p>					

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Abstract of cost					
1/15.1 Restoration of Raincoats/Berms do do all complete job. Qty VTM B P. No - (48) 87.084 ² @ 378 = 32944 ²⁰					
2/15.2 Making up Berms/shoulder etc do do all complete job. Qty VTM B P. No - (49) 292.504 ² @ 57 = 16713 ²⁰					
3/15.5 Repair of pot holes do do all complete job. Qty VTM B P. No - (49) 60.944 ² @ 373 = 22773 ²⁰					
4/15.6 (i) Patch Repair over pot holes do do all complete job. Qty VTM B P. No - (49) 60.944 ² @ 313 = 19133 ²⁰					
5/15.6 (iii) Patch repair over bituminous surface with 20mm premix etc Qty VTM B P. No - (50) 60.944 ² @ 331 = 20228 ²⁰					
7/15.7 (i) Maintenance of C/D work etc. Qty VTM B P. No - (50) - 1.010 ² @ 1109 = 1110 ²⁰ 11290 ²⁰					

