

Koceri Purani Told to LO75

17070658-5C

Schedule XLV Form No. 134.

Executive Engineer, R.W.D. DIVISION
Tekari

Assistant Engineer, R.W.D. SUB-DIVISION
Tekari.

Measurement Book

908

DINESH KUMAR

2nd year maintⁿ bill



55

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - Koeri Purbi-tola					
to Lot 5					
Agency - Dinesh Kumar					
Agreement no - 35 SBD/mmsy 121-22					
Date of start of work - 19/05/21					
Actual completion date - 14/05/22					
1. Restoration of rain-cuts					
do					ent = 39.97m
2. Making up of berms/shoulder					
do					
					ent = 222.08m
3. Repair of pot holes filled with 75mm WBM					
do					ent = 0.09m ³
4. Patch repair over pot holes					
do					ent = 30.84m ²
5. Patch repair over bituminous surface					
do					ent = 30.84m ²
6. Crack-sealing-filling of cracks					
do					ent = 658m
7. maint ⁿ of c/p works					
hume pipe					ent = 4 NO.

Continuation



Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(8) Maint ⁿ of road sign do				ent =	0.66 km
(9) Maint ⁿ of 200 m 8 km stone do				ent =	0.66 km
(10) cutting of branches of trees & shrubs do				ent =	4 No.
(11) cutting of shrubs from roadways do				ent =	658 No.
(12) Trimming of greens and weeds do				ent =	1481 m ²
(13) white washing of parapet walls of CD works do				ent =	84 m ²
Gairah 11/05/24 JE  20/05/24 AE					
material statement					
(1) E/W =	63.289 m ³				
(2) stone metal aggregates =	1.774 m ³				
(3) Bitumen 10 =	0.1171 MT				
Gairah 11/05/24 JE  20/05/24 AE					

Abstract of cost

57

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1. Restoration of rain cuts					
ent =	39.97 m ³			P- (55)	
ctm - (1) @ Rs		404.06 =		Rs	16150 =
2. making up berms / shoulder					
ent =	222.08 m ²			P- (55)	
ctm - (2) @ Rs		60.28 =		Rs	13387 =
(3) Repair of pot holes filled with 75mm WBM					
ent =	0.09 m ³			P- (55)	
ctm - (3) @ Rs		8700.73 =		Rs	783 =
(4) Patch repair over pot holes					
ent =	30.84 m ²			P- (55)	
ctm - (4) @ Rs		229.62 =		Rs	7081 =
(5) Patch repair over bituminous surface					
ent =	30.84 m ²			P- (55)	
ctm - (5) @ Rs		245.71 =		Rs	7578 =
(6) Crack-sealing-filling of cracks					
ent =	658 m			P- (55)	
ctm - (6) @ Rs		3.71 =		Rs	2441 =

Continuation



Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
⑦ Maint ⁿ of c/o works hume pipe do					
ent = 4 No. P- (55)					
itm - (7) @ Rs 1166.58 = Rs					46662
⑧ Maint ⁿ of road sign do					
ent = 0.66 km P- (56) (56)					
itm - (8) @ Rs 1104.59 = Rs					7292
⑨ Maint ⁿ of 200 m of km stones do					
ent = 0.66 km P- (56)					
itm - (9) @ Rs 643.17 = Rs					4242
⑩ cutting of branches of trees & shrubs do					
ent = 2 No. P- (56)					
itm - (10) @ Rs 113.64 = Rs					2272
⑪ cutting of shrubs from roadway do					
ent = 658 No. P- (56)					
itm - (11) @ Rs 6.98 = Rs					4593
⑫ Trimming of grass and weeds do					
ent = 14181 m ² P- (56)					
itm - (12) @ Rs 2.33 = Rs					34512

Continuation

Continuation