

Home Se (Raghuvver Singh ke Ghar) to Harjain
Tola Hote Huye mmbsy Sadak tak. Mmbsy (sc)

Schedule XLV Form No. 134.

MAHNR

DIVISION

JAN DIHA

SUB-DIVISION

Measurement Book

— 672

Sch. XLV-Form No. 134

Sch. XLV-Form No. 134					Contents of area
Particulars	Details of actual measurement				
	No.	L.	B.	D.	
3rd year main.					
N/W :- HOME SE ROAD ROAD					
Raghuvendra Singh ke					
ghat to HORIZON tola					
note huge mmusy sadak					
Agency - Madhukendra K.S.					
AGB No - 88/MMUSY/20-21					
Dt of Comm - 4/9/20					
Dt of Actual completion - 21/2/21					
RECORD entry -					
Restoration of kerbs					
$14 \times 2.09 \times 2 \times .75 \times 30 = 13.16$					

$$10 \times 2.20 \times 2 \times .60 \times 30 = 7.92$$

$$16 \times 1.96 \times 2 \times .80 \times 30 = 8.14$$

$$= 29.22 \text{ m}^3$$

$$\text{Limit} = 28.35 \text{ m}^3$$

$$2. \text{Main of road sign}$$

$$= .06 \text{ K.M}$$

$$3. \text{Main of road sign}$$

$$\text{and K.M stone}$$

$$= .07 \text{ K.M}$$

$$4. \text{Plastering of hot}$$

$$\text{applied thermoplastic}$$

$$400 \times 2 \times .10 = 80 \text{ m}^2$$

Continuation

2.32
m

21/3/21
J.V

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>Abstract of cost</u>					
1. Restoration of rain cuts					
Esty 1490 T.M.B.P-48					
= 28.35 m ³					
@ RS 400 = 71/m ³					RS 11360.
2. Main of road sign					
Esty 1490 T.M.B.P-48					
= .06 K.M					
@ RS 1118 = 49/K.M					67.0
3. Main of 200 m and K.M stone					
Esty 1490 T.M.B.P-48					
= .07 K.M					
@ RS 640 = 68/K.M					45.0
4. P/V and raising of					
not applied the masonry					
Esty 1490 T.M.B.P-48					
= 80 m ²					
@ RS. 735 = 44/m ²					RS 58835.
					RS 70307.00
Add 12.17 ST					RS 8437.00
Add 1. L.C					RS 703.00
					RS. 79447.00
LESS 11.20 T. below					
RS 11.20 T. below					RS. 8898.00
					RS 70549.00
Continuation					

2.2.1
A2

10/11/16
2/3/24
S.D