

2nd year Maintenance Bill

75

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	

Abstract of cost

(1) Restoration of Rain cuts.

124.24 m³ Qty Vide P.No. 72

Rs 396.73 /- R₂: 49,408:00
49,289:00

(2) Making up of berms shoulder.

891.00 m³ Qty Vide P.No. 72

Rs 89.87 /- R₂: 41,370:00

(3) Pot repair over ~~sub~~ bituminal surface. with 2 mm gres.

58.48 m² Qty Vide P.No. 72

11.70.2 Dry Vide P.No. 73

@ 2.24 / — Rp: 26:00

10) Main of already admitted
one of additional.

63. No Dry Vide P.No. 73

@ 671 / — Rp: 42,273:00

To: 1,55,490:00

Add w.s. Title 13% @ = 20,213:00

To: 1,75,703:00

less for below 520% (G) = 91,36:00

To: 1,84,839:00

Muzabo
JE 15/7/24

Single

15.07.24

CRP
Continuation
76/7/24
AE