

XXXXGIS

2

R.M.D. Morris Division

DIVISION

SUB-DIVISION

M.D.N-3562

Measurement Book

$\frac{\text{अनुमानित}}{\text{अनुमानित}} = \frac{\text{अनुमानित}}{\text{अनुमानित}}$

(MM 657-50)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/wout - Maintenance of Road from					
Koyam Pasikhana to					
Majhiama tola.					
Agency - Md. Sahban					
Ag. No - 09-SRD/20-21					
D/Start - 13/6/20					
Act. Coupli - 8/3/21 28/5/21					

Measurements:

(1) Restoration of drain-cuts with.

Soil, murrum etc as per Spalte

$$1 \times 9.0 \text{ cut} \times 0.40 \times 0.300 = 1.13 \text{ m}^3$$

$$2 \times 11.30 \text{ cut} \times 0.85 \times 0.300 = 5.76 \text{ m}^3$$

$$1 \times 12.75 \text{ cut} \times 0.90 \times 0.300 = 5.87 \text{ m}^3$$

$$2 \times 28.30 \text{ cut} \times 0.75 \times 0.300 = 12.74 \text{ m}^3$$

$$2 \times 2 \times 7.50 \text{ cut} \times 0.70 \times 0.300 = 6.30 \text{ m}^3$$

$$1 \times 18.75 \text{ cut} \times 0.80 \times 0.300 = 4.50 \text{ m}^3$$

$$3 \times 2 \times 2 \times 3.50 \text{ cut} \times 1.10 \times 0.300 = 13.86 \text{ m}^3$$

$$\text{Total} = 40.92 \text{ m}^3$$

$$\text{Left} = 36.48 \text{ m}^3$$

(2) Maintenance of earthen.

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Abstract of Cost					
(1) Restora. of Rain-cuts					
Vide T.M.B, HM-1, P-26					
= 36.40 m ²					
@ Rs-379.59/m ² - Rs-					13,817 =
(2) Maint. of Shoulders					
Vide T.M.B, HM-2, P-26/27					
= 202.50 m ²					
@ Rs-56.81/m ² - Rs-					11,504 =
(3) Maint. of 11 P Culverts					
Vide it-3, P-27 = 0.2 Nos					
@ Rs-1162.80/each - Rs-					2206 =
(4) Maint. of 8 Sub Culverts					
Vide it-4, P-27 = 0.1 No					
@ Rs-2273.47/m ² - Rs-					2273 =
(5) Maint. of Road Signs					
Vide T.M.B, HM-5, P-27 = 0.600 Km.					
@ Rs-1054.28/km - Rs-					633 =
(6) Maint. of K.M. Stones					
Vide it-6, P-27 = 0.600 Km.					
@ Rs-651.92/km - Rs-					391 =

Continuation