

Particulars	Details of activity, capacity, content				Contents excess
	No.	L	B	D	
6th year period					
Name of work: -					
Lead from Bhamra 17-20					
Attached to Bhamra 17-20					
Package No. - 17-20					
13.10.2018					
Agency: -					
Ans: -					
17 Williams, Taron					
Neighbour (Thurkland)					
Hgg No. -					
IND 132 f 2018-19					
Date of egg					
22.10.2018					
Date of completion					
21.10.2019					

Record Entry

① Restoration of Riments/

Beams with soil maximum

5X	3.20X	1.00	X 0.30	= 5.76 m ³
6X	4.20X	1.15	X 0.20	= 5.52 "
8X	4.20X	1.20	X 0.30	= 9.60 "
6X	2.40X	0.90	X 0.30	= 3.33 "
8X	5.50X	1.15	X 0.25	= 12.65 "
7X	3.50X	1.08	X 0.20	= 5.29 "
6X	4.20X	1.20	X 0.30	= 8.64 "
9X	4.75X	0.90	X 0.30	= 11.54 "
6X	4.60X	1.10	X 0.20	= 7.59 "
8X	3.20X	1.20	X 0.30	= 8.64 "
3X	3.75X	1.20	X 0.30	= 4.55 "

(Continuation)

Attested

Pritham
12/07/24

Bh. XIV Form No. 101

Particulars	1	2	3	4	5
Area of lot of					
42.5 m ² main lot					
① Destruction of boundary					
Removal with soil material					
100.00 m ² vide TRB P No. (12)					
@ R. 53.00/m ² — — — — R.					35510.00
② Making up of boundary					
shoulder, stripping excess					
soil from the shoulder					
752.80 m ² vide TRB P No. (13)					
@ R. 53.00/m ² — — — — R.					40127.00
③ Repair of pot holes filled					
with 75 mm WBSM					
9.10 m ² vide TRB P No. (13)					
@ R. 376.35/m ² — — — — R.					3462.00
④ Patch repair on already					
filled pot holes with 75 mm					
154.41 m ² vide TRB P No. (20)					
@ R. 245.10/m ² — — — — R.					30493.00
⑤ Repair to pot holes and					
removal of loose materials					
124.13 m ² vide TRB P No. (21)					
@ R. 263.08/m ² — — — — R.					32731.00
⑥ Maint. of ops works					
on Nos. vide TRB P No. (22)					
@ R. 1131.04/each — — — — R.					4527.00

(Continuation)

[illegible]

Attested
Priyam
12.07.24

Priyam
12.07.24

12.07.24

(Continuation)