

05 SBD/2019-20

Garkeli To Kerket Tola

(Mmghy-5c)

Measurement Book - 1619

Schedule XLV-Form No. 134

Raisi

DIVISION

Amour

SUB-DIVISION

Abdus Malik

1st year Maintenance

1

Name of Work -

Situation of work -

Agency by which work is executed -

Date of measurement -

No. and date of agreement -

(These four lines should be repeated at the commencement of the measurements relating to each work).

[illegible]

① Restoration of air cuts/			
beds with soil moisture.			
2x	5.5017x	0.85017x0.3017x	2.81 M ³
3x	4.6017x	0.85017x0.3017x	2.88 M ³
2x	6.6017x	0.90017x0.3017x	3.24 M ³
3x	3.4017x	0.95017x0.3017x	2.99 M ³
2x	7.0017x	0.80017x0.3017x	2.94 M ³
2x	7.5017x	0.70017x0.3017x	3.15 M ³
2x	8.5017x	0.75017x0.30017x	3.83 M ³
3x	4.4017x	0.85017x0.3017x	3.44 M ³
1x	7.6017x	0.75017x0.3017x	3.83 M ³
Total			29.11 M ³

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(2/2) Making up of borrow shoulder stripping excess soil from the shoulder.					
1x	16.50M	0.95M			15.68M ²
1x	12.00M	1.15M			13.80M ²
1x	13.00M	1.20M			15.60M ²
9x	9.50M	1.20M			11.40M ²
1x	14.00M	1.05M			14.70M ²
1x	18.00M	0.80M			14.40M ²
1x	22.00M	0.70M			15.40M ²
1x	16.00M	0.85M			13.60M ²
1x	12.50M	1.10M			13.75M ²
1x	17.00M	0.90M			15.30M ²
1x	19.50M	0.85M			16.58M ²
1x	14.50M	1.15M			16.68M ²
1x	13.00M	1.10M			13.10M ²
			Total Qty.		189.89M ²
					189.84M ²
(3/5) Patch repair over bitu- minious surface with 20mm Mix 50:50 Surfacing.					
1x	2.00M	1.15M			2.30M ²
1x	2.75M	1.25M			3.44M ²
1x	1.90M	1.25M			2.38M ²
1x	1.50M	1.45M			2.17M ²
1x	2.90M	1.10M			3.19M ²
			Total Qty.		13.48M ²

Continuation

Continuation

Sch. XLV-Form No. 134

A.B.C./2019/1051

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work / Part of Rd / Km					
6/20/19 to Rev 1/70/19					
Agency - Abdul Malik					
Agreement No - 0556 D/2019-20					
Date of Commencement - 25/06/19					
Actual Date of Comp/10/10/19					
(1) Restoration of drains / berms with soil/grass					
29.11 m ³ Q.V. T.M.B.P. 151					
@ Rs 365.75/m ³ Rs					10632.00
(2) Making up of berms / shoulder stripping excess soil, for mtl shouder					
189.84 m ² Q.V. T.M.B.P. 251					
@ Rs 54.16/m ² Rs					10282.00
(3/5) Patch repair over bitu- minious surface with 20mm Mix Seal Surfacing.					
13.48 m ² Q.V. T.M.B.P. 251					
@ Rs 217.92/m ² Rs					2937.00
(4/7) Maintenance of H.P. Culvert					
1.00 Nos Q.V. T.M.B.P. 351					
@ Rs 1131.64/each Rs					1132.00
(5/9) Maintenance of Road sign					
0.07 Km Q.V. T.M.B.P. 351					
@ Rs 1087.62/Km Rs					76.00
(6/10) Maintenance of 20/19nd					

Continuation

C/o Rs 25,059.00

