

Const of Road from DHUNTA TOLA TO MUSLIM TOLA
REORNA (TALE BLOCK)

Schedule XLV-Form No. 134

(MM45Y-S.C)

Executive Engineer

R. W. D. (W) Division

DIVISION

Barbados

Jale SUB-DIVISION

AG. No: 104/580/2020-21

AG. Amount Rs: 01,92,80.942=00

Measurement Book

M/S PRITOSH CONSTRUCTION

No. 909

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	<u>ABSTRACT of COST</u>				
$\frac{1}{15.1}$	Restoration of culverts/ Berons with soil cul up. vide TMB p. No-64 94002/4 3.98 m ³ @ 404-06/m ³ — 58176-00				
$\frac{2}{15.2}$	MAKING up of Berons/ show cul with all comp. vide TMB p. No-64 94002/4 7.99-88 m ² @ 60-28/m ² — 48216-00				
$\frac{3}{15.701}$	Maint. of C/D 000250 Hume pipe culverts with all comp. vide TMB p. No-65 94002/3 8.908. @ 1166-58/No — 9333-00				
$\frac{4}{15.9}$	Maint. of road signs with all comp. vide TMB p. No-65 94002/4 2.37 KM @ 1104.58/KM — 2618-00				
$\frac{5}{15.11}$	Maint. of 200M and KM stone with all comp.				

B-118343 200

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	vide TMS	D. No - 66			
	9/1 (5)	2.37	km		
		as 678-11/100			1607200
6/15/2011	Cutting of branches				
	of trees and shrub				
	with all comp.				
	vide TMS	P. No - 66			
	9/1 (5)	4 nos.			
		as 113-641 No			455200
7/15/2011	Trimming of grass and				
	weeds with all comp.				
	vide TMS	P. No - 66			
	9/1 (7)	50.10 m			
		as 16-89/m			845200
8	Maint. of Already planted				
	trees for Additional				
	four year Maint. of trees				
	by the road side etc.				
	vide TMS	P. No - 66			
	9/1 (8)	159 nos.			
		as 688.00/100			109392200
					6-230642200
	Add 12% C.S.				27677200
	Add 1% L. ass.				2306200
	Free				501200
					8-261/26200
	Less 4.53% Belong				1/829200
					8-249297200

 Nikhil
 24/09/2024
 AE

Atymer
 24/3/2024
 OE