

MMGSJ (SC)

Schedule XLV-Form No. 134

DIVISION

SUB-DIVISION

TABLE

MEASUREMENT BOOK

OM Shanti Construction

No. 241

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	ABSTRACT OF COST				
1.	Restoration of Rainwater				
	berms with soil on				
	comp.				
	vide TMS p. No - 67				
	9 ft (1) 63.32 m ³				
	at 398.45/m ³				25230.2w
2.	Making up of berms				
	shoulder with soil				
	on comp.				
	vide TMS p. No - 67				
	9 ft (2) 350.85 m ²				
	at 54.16/m ²				19002.2w
3.	Repair of pot holes				
	filled with 75 mm				
	thick red comp.				
	vide TMS p. No - 69				
	9 ft (8) 3.43 m ³				
	at 10382.68/m ³				35611.2w
4.	Patch Repair over pot				
	holes with comp.				
	vide TMS p. No - 69				
	9 ft (4) 45.70 m ²				
	at 221.14/m ²				10106.2w
					/
					89949.00

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
5.	Maint. of C/D in Hume				
	bike culvert all comp.				
	wide TMS p. No. 68				
	9/11 (3) 3 nos.				
	QS 1131-34/No				3395=w
6.	Cutting of branches of				
	trees/shrubs all comp.				
	wide TMS p. No. 68				
	9/11 (4) 2 nos.				
	QS 118-23/4				2362=w
7.	Cutting of shrubs from				
	road side all comp.				
	wide TMS p. No. 68				
	9/11 (5) 7 nos.				
	QS 6.60/No				462=w
8.	Trimming of grass				
	all comp.				
	wide TMS p. No. 68				
	9/11 (6) 17.0 m ²				
	QS 2.20/m ²				372=w
9.	White washing of parapet				
	road all comp.				
	wide TMS p. No. 68				
	9/11 (7) 25.98 m ²				
	QS 15-98/m ²				415=w
					44078=w

Continuation

[illegible]

Continuation