

सुदूरपश्चिम प्रदेश मापन विभाग
सुदूरपश्चिम प्रदेश मापन विभाग
सुदूरपश्चिम प्रदेश मापन विभाग
Schedule XLV-Form No. 134
S.C.

सुदूरपश्चिम प्रदेश - सुदूरपश्चिम प्रदेश
DIVISION

सुदूरपश्चिम प्रदेश - सुदूरपश्चिम प्रदेश
SUB-DIVISION

Measurement Book

MR No. - 3054

5th year Maintenance Bill

62

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/W - Maintenance of Road					
from Nayaga Bazar					
Samanta to Pokhar blind					
N/Aging - Soil chandam prakash					
Agg. No - 64 SBD / 2017 - 18					
A.D.O.C - 29.09.2018					
Date of measurement - 30.9.2023					
(1) Restoration of drain					
of soil - do - do etc.					
	10x	3.60x	.650x	.30	= 7.024 ³
	12x	2.70x	.50x	.30	= 4.864 ³
	10x	2.50x	.625x	.30	= 4.694 ³
	15x	4.30x	.600x	.30	= 11.614 ³
	12x	4.60x	.625x	.30	= 10.354 ³
	10x	5.40x	1.125x	.30	= 16.8754 ³
	15x	6.30x	1.12x	.30	= 23.754 ³
					87.1554 ³
					limited - 86.574 ³
(2) Making up of Bottom					
Shoulder - do - do etc.					
	10x	5.20x	1.125x		= 58.504 ²
	15x	3.70x	1.125x		= 62.444 ²
	12x	5.60x	1.120x		= 75.264 ²
	10x	6.250x	1.25x		= 196.204 ²
					limited - 192.384 ²
(3) Repair of pot holes filled					
with Fe 44 19BAP.					
	10x	.70x	.50x		= 3.504 ²

Continuation

Co 3.504²

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
			B.P.		3.5042
	5x	1.10x	1.00	=	5.5042
	10x	1.20x	1.10	=	13.2042
	6x	.625x	.625	=	2.3443
	12x	1.50x	1.20	=	21.6043
					46.1443
			Limited		44.5343
④ patch repair A pot					
			holes	40	40
			etc.		
	10x	.70x	.50	=	3.5042
	5x	1.10x	1.00	=	5.5042
	10x	1.20x	1.10	=	13.2042
	6x	.625x	.625	=	2.3442
	12x	1.50x	1.20	=	21.6042
					46.1442
			Limited		44.5342
⑤ patch repair cur					
			B.T. surfaces	10	
			etc.		
	15x	1.20x	1.10	=	19.8042
	10x	1.10x	1.00	=	11.0042
	10x	1.20x	1.10	=	13.2042
					44.0042
⑥ Maintenance A & D					
	1200K	HPC			0.11K
⑦ Maintenance B & C					
	1200K				0.14K

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>ABSTRACT OF COST</u>					
① Restoration of rain cent					
A. Soil do					
vide T.M.B.P. — (62)					
86.574 ³	@	₹ 361.86/4 ³			₹ 31326.00
② Making up B. Birm /					
swarder.					
vide T.M.B.P. — (62)					
192.384 ²	@	₹ 57.61/4 ²			₹ 10506.00
③ Repair A pot holes do					
do etc.					
vide T.M.B.P. — (63)					
44.534 ²	@	₹ 347.60/4 ²			₹ 15479.00
④ Patch repair of pot holes					
do do etc.					
vide T.M.B.P. — (63)					
44.534 ²	@	₹ 118.33/4 ²			₹ 5269.00
⑤ Patch repair cur B.T					
Surface.					
vide T.M.B.P. — (63)					
44.004 ²	@	₹ 107.53/4 ²			₹ 4731.00
⑥ Maintenance A road					
Sign					
vide T.M.B.P. — (63)					
0.14 KM	@	₹ 1034.49/KM			₹ 145.00
⑦ 200 y stone.					
vide T.M.B.P. — (63)					
0.23 KM	@	₹ 556.14/KM			₹ 128.00
Continuation					₹ 67584.00

