

5th year maintenance
42

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
New: TO ₂ NH land no 5 to					
hatchpur Bala land no-11					
Agency: M/s Anshu Kumar Singh					
Aggr. No. 37 (SRO) of 2018-19					
D.O. No. 18 DS. 2018					

Date of actual Comp- 10.02.2019

Date of measurement -

Details -

① Restoration of Boundary -

L.H.S	25	2.40	1.10	0.35	23.10
	15	2.15	0.90	0.30	8.71
	26	2.65	0.95	0.30	19.64
	20	2.25	1.40	0.35	22.05

R.H.S	13	2.20	1.20	0.30	13.46
	16	2.40	1.15	0.35	13.52
	18	2.40	1.00	0.30	10.80
	24	1.75	1.10	0.35	14.15
	24	2.35	1.20	0.35	23.69
					149.12 m ³

② Maintenance of Pathway

Shoulder -

L.H.S	15	10.00	0.75		112.50
	12	15.00	0.85		153.00
	11	8.00	0.90		79.20
	20	6.00	0.80		96.00
	25	8.00	0.75		150.00
R.H.S	20	9.00	0.80		144.00

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>Abstract of cost</u>					
① Restoration of Rain Cuts —					
Qty with THB R (92)					
L-148.53 m ³ @ R 372.27/m ³ — R 55368 =					
② Maint. of earthen shoulder —					
Qty with THB R (42)					
L-825.19 m ³ @ R 56.01/m ³ — R 46219 =					
③ Repair to pot holes —					
Qty with THB R (42)					
L-116.03 m ² @ R 219.67/m ² — R 25488 =					
④ The maint. of curby kerb —					
Qty with THB R (43)					
L-116.03 m ² @ R 219.67/m ² — R 25488 =					
⑤ Patch repair on already filled					
Qty with THB R (43)					
258.32					
L-116.03 m ² @ R 258.32/m ² — R 29973 =					
⑥ Maint. of Road sign —					
Qty with THB R (43)					
1.63 Km @ R 1067.44/Km — R 1740 =					
⑦ Trimming of grass —					
Qty with THB R (43)					
L-2292.19 m ² @ R 2.14/m ² — R 4905 =					
G. 189181 =					
Less Below 10 % — — — — — R 18918 =					
R 170263 =					
 20/04/24 SC					