

Sch. XLV - Form No. 134

Sch. XLV - Form No. 134					Contents of area
Particulars	Details of actual measurement				
	No.	L.	B.	D.	
Name of Road -	Maintenance of Road from				
Mahalpur - Tetmuran Daryapur Road in					
Chauri Ashan to Primary school Chauri.					
Agency -	Pune Global Infra.				
App. No -	SBD-24/2012-18				
Actual date of completion -	25.01.2019				

Heavy

D Restoration of drain cuts

.....201.....	201.....	201.....	201.....	201.....
14	0.65	1.00	0.30	2.730 m ³
12	0.80	1.00	0.30	2.880 m ³
10	1.15	0.90	0.30	3.105 m ³
8	1.45	0.90	0.30	3.132 m ³
6	1.95	0.90	0.30	3.159 m ³
4	2.35	0.90	0.30	2.538 m ³
6	2.60	0.90	0.30	4.212 m ³
8	1.85	0.95	0.30	4.218 m ³
1	5.05	0.90	0.30	1.364 m ³
32	2.22	1.22	0.30	27.338 m ³

D Maintenance of earthen shoulder

.....201.....	201.....	201.....	201.....	201.....
12	4.60	0.90		49.68 m ²
8	6.90	0.90		49.68 m ²
6	3.40	0.90		39.96 m ²
1	13.95	0.90		12.56 m ²
32	2.22	1.22	0.30	151.88 m ²

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
② Repair of Pot holes filled with gum BH					
.....					
	8X	0.80X	0.60X	0.075	0.2884 ³
	12X	0.60X	0.50X	0.075	0.2704 ³
	8X	0.90X	0.75X	0.075	0.4054 ³
	6X	1.15X	0.90X	0.075	0.4664 ³
	4X	1.50X	1.20X	0.075	0.5404 ³
	3X	2.35X	1.25X	0.075	0.6614 ³
					2.6304 ³
④ Patch repair over Pot holes					
.....					
	8X	0.80X	0.60		3.8442
	12X	0.60X	0.50		3.6042
	8X	0.90X	0.75		5.4042
	6X	1.15X	0.90		6.2142
	4X	1.50X	1.20		7.2042
	3X	2.35X	1.25		8.8142
					35.0642
⑤ Patch repair over B.T. surface					
.....					
	8X	0.70X	0.60		3.3642
	7X	0.80X	0.65		3.6442
	4X	0.90X	0.75		2.7042
	2X	1.25X	0.90		4.0542
	4X	1.60X	1.15		7.3642
	2X	2.25X	1.25		5.6342
	2X	2.95X	1.40		8.3242
					35.0642

Continuation

ABSTRACT OF COST

Continuation

Continuation