

3rd year maintenance

Sch. XLV-Form No. 134 44

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	

N/w. Maintenance of Road from
Kauri Simari RFO Path ke
Hanuman mandir se aghe tole
Somnath.

Agency - Bhole Kumar

Ag. No. 37 SBD/2020-21

D.O.W. 16.09.2020

Actual D.O.C. 30.04.2021

① Restoration of RainCut -

RHS - $25 \times 1.50 \times 0.75 \times 0.35 = 9.84$

LHS - $20 \times 1.75 \times 0.90 \times 0.35 = 11.02$

RHS - $30 \times 1.45 \times 0.80 \times 0.30 = 10.44$

LHS - $22 \times 2.00 \times 0.60 \times 0.30 = 7.92$

RHS - $26 \times 2.15 \times 0.70 \times 0.35 = 13.69$

LHS - $20 \times 0.75 \times 0.45 \times 0.30 = 2.02$

RHS - $20 \times 2.25 \times 0.85 \times 0.35 = 13.39$

LHS - $05 \times 1.90 \times 0.70 \times 0.30 = 1.99$

70.31 m³

② Making up of Berms of Shoulder -

LHS - $20 \times 4.00 \times 0.75 = 60.00$

RHS - $25 \times 5.00 \times 0.70 = 87.50$

LHS - $05 \times 8.00 \times 0.85 = 34.00$

RHS - $10 \times 10.00 \times 0.80 = 80.00$

261.50 m²

③ Repair of hot holes with

75mm WBM

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	

B.H - R-244202 =

Adj. 6st + L. corr 13% - (+) R 31746 =

Adj. S. Fee - (+) - R 780 =

R 276728 =

Less Below 15.57% - (-) R 42921 =

42920 =

R 233807 =

12/06/24

JL

MaterialQty. 95.677 m³S/cupr - 2.658 m³S/melay - 4.479 m³

RS-1 - 0.025 MT

L90 - 0.210 MT

12/06/24

JL