

Lo 55 To PENDING PURCHASE

(S.C.)

Agreement No - 105/SAD/2020-21 HEAD:- M.M.G.S.Y.

32

Schedule XLV-Form No. 134

DIVISION

Gurgaon

SUB-DIVISION

1208

Measurement Book

File No:- 3-15121 572112

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1st year maintenance bill					
N/W - Maintenance of road					
from loss to pendapurdi					
Agency - Ajay Kumar					
Agreement No - 105/SBD/2020-21					
date of Agreement - 05.3.2021					
date of completion 4.12.2021					
Actual date of compn					
below 17.5%					
HAND (M) OF DIVISIONAL ACCOUNTS OFFICE					HAND (M) OF EXECUTIVE ENGINEER
date of entry					

(1) 10.10	Repair of old joint				
	self-repair				
	537 M x 1/2 =				537 M
(2) 15.2	Maintenance of drain				
	drain				
	02 nos				
(3) 16.9	Maintenance of road sign				
	0.580 km				
(4) 15.11	Maintenance of 200m				
	8 km 820 m				
	0.580 km				

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(5) 15.12.11					
White washing of					
perimeter of compound					
2 x 6.15 x 1.20 =					12.22 m ²
4 x 0.40 x 0.6 =					0.96 m ²
2 x 0.60 x 0.40 =					0.48 m ²
					37.32 m ²
(6) 5.11.12					
Repair of old isolated - chub					
2 x 18 x 0.40 =					14.4 m ²
					13.48 m ²
(7)					
Entry of Branch office ch					
02 nos -					

Continuation

Continuation PC 1927524

Enrollment

39
Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
2nd year maintenance					
N.W. loss to pond & pump					
Agency Ajay Kumar					
Agreement - 105 SBZ/2020-21					
date of Agmt -		8.3.2021			
date of comp -		4.12.2021			
Actual date of comp -					
Below 12.5%					
date of entry -					
(1) Repair of concrete					
payment done					
$22 \times 2.00 \times 0.60 =$					$26.40 m^2$
$2 \times 18 \times 0.40 =$					$14.40 m^2$
					$T = 40.80 m^2$
(2)					40.80 m ²
Repair of old joint					
sealant done					
5.35 m					
(3) Maintenance of (2)					
work done					
0.2 m ²					
(4) Repair of road sign slab					
0.580 m					

Continuation

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
					At 5 to 9 of cost.
(1)	Repair of concrete pavement				
	ab-clo. 84y side				
	trap-39 item 1				
	40.8 m ² @ 249.38/m ² =				10175.20
(2)	Repair of joint sealant				
	ab-clo 84y side Trap.				
	Page no 39 item 2				
	539 m ² @ 23.49/m ² =				12660.20
(3)	Maintenance of				
	works at				
	84y side Trap-39				
	item 3				
	02 m ² @ 1130.62/m ² =				2261.20
(4)	Maintenance of road				
	84y side				
	84y side Trap-39				
	item 4				
	0.53 m ² @ 1072.18/m ² =				568.50
(5)	Maintenance of				
	road at				
	84y side				
	item 5				
	0.94 m ² @ 631.44/m ² =				594.15
Continuation of					

Continuation