Observation Details

Monitor	D. Ravi Karthikayan	State	Bihar	District	Supaul
Road Name	L053-T01 To Koriapatti Yadav Tola (ODR28)	Bridge Name	Koriapatti dhar		
Sanction Year	2017-2018	Package	BR35R190	Length (Mtrs.)	132.70
Road Status	Maintenance	Completion Date		Inspection Date	21-Sep- 2022

Note : Overall Grading denotes, [ U - No Maintenance | SRI - Low Maintenance | S - Maintenance Not Required / Proper Maintenance ]

Sr.No.	<b>Item Description</b>	Grade	Remarks
1	<b>Quality Arrangements</b>	Not Applicable	-
	1. Quality Arrangements	Not Applicable	-
2	Foundation ( Stage I)	Not Applicable	-
	1. Foundation ( Stage I)	Not Applicable	-
3	Sub-Structure ( Stage II)	Not Applicable	-
	1. Sub-Structure ( Stage II)	Not Applicable	-
4	Super-structure ( Stage III)	Unsatisfactory	-
	1. Super-structure ( Stage III)	Unsatisfactory	wearing coat top surface spalling out
5	Contraction joint according to IS code	Not Applicable	-
	1. Spacing ( To be indicated as observed)	Not Applicable	-
	2. Cross Section	Not Applicable	-
6	Bearing -(Grading to be same as for condition of Bearing)	Unsatisfactory	-
	1. A. Type of Bearing- Rocker and Pin Bearing, Roller Bearing, Pot Bearing, Elastomeric Bearing, Any other Bearing)	Not Applicable	-
	2. B. Condition of bearing	Unsatisfactory	Bearing supports used during fixing is not yet removed

7	7	Approaches ( Stage II & III)	Required Improvement	-	
		1. Embankment	Required Improvement	-	
		2. Sub Base (G.S.B)	Not Applicable		
		3. Base Course (Non Bituminous(WBM) and Bituminous(BM))	Not Applicable	-	
		4. Bituminous Surface Course-OGPC/SDBC	Not Applicable	-	
		5. Wearing Course	Not Applicable		
8	8	<b>Bridge Furniture and Markings</b>	Satisfactory	-	
		1. Main information Board	Satisfactory		
		2. Citizen Information Board	Satisfactory		
		3. Logo Board	Satisfactory		
		4. Guard stone on approaches	Not Applicable		
		5. Mandatory and Caution signage	Not Applicable		
1	0	Overall Grading	Unsatisfactory	-	
	Overall Grading - Unsatisfactory				