

2nd year Maintenance

Particular	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/W -	Mainten	4.9	2.2	20m	KEV
					Bali Belwa se Pachaukha Hole
					Gua to Pipers Jabhakar.
					MMSY (W.B.)
Block -	Kalyanpur				
Agency -	Suresh Ch Singh Consts Pvt Ltd.				
	Mallika Street Jabhakar.				
	E. Chhapra.				
Agreement No -	33/BD/2020-21				
Actual Date of Comp -	31.3.2020				
	Maintenance work has been				
	done by Agency				
✓	Restoration of Rain				
	cuts with soil				
	2x	6 x 12.10	x 0.80	x 0.20	23.23
	2x	10 x 9.90	x 0.70	x 0.20	27.72
	2x	14 x 6.80	x 0.60	x 0.20	22.24
	2x	18 x 3.52	x 0.50	x 0.20	12.67
					T 86.4673
2.	Filling up of Shm Hm				
					filli:
	2x	5 x 14.20	x 0.75		= 106.50
	2x	7 x 12.60	x 0.85		= 149.94
	2x	9 x 10.40	x 0.70		= 131.04
	2x	11 x 8.50	x 0.80		= 149.60
	2x	13 x 6.70	x 0.75		= 130.65
	2x	15 x 5.30	x 0.80		= 127.20
	2x	17 x 4.10	x 0.70		= 97.58
	2x	14 x 3.00	x 0.65		= 54.60
	2x	12 x 7.30	x 0.60		= 105.12

Continuation

Particular	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
T-1	4	6.150	0.40		9.84
	18	2.50	0.40		18.00
Final	44	0.40	0.60		10.56
S.L.	4	6.150	0.60		14.76
	18	2.50	0.60		27.00
				T	80.16 m ²
				with	42.00 m ²
10	Maintaining Road sign				
	by way				0.40 km
11	Maintaining 200 yd KM				
12	stone by way				0.50 km
<div style="display: inline-block; text-align: left; margin-right: 50px;"> 23/09/24 </div> <div style="display: inline-block; text-align: left;"> 24/10/24 AR </div>					

Abstract of cost.				
1	Restoration of Rain			
	cub			
	P.			
86.46 m ³	406.82		2.	35174.00
2/2	Making up of shoulder			
	filling			
	P.			
1125.56 m ²	61.70		6.	69447.00
2/5	Patch of air over			
	bitumin surf			
	P.			
100.08 m ²	276.43		6.	27665.00
4/7	Maintaining old work over			
	H.P culvert			
	P.			
2 No of	1130.67		!	2261.00

Continuation

