

BACHHI PASI KE LOHAR To BRAHMAN
Toli Schedule XLV-Form No. 134

BENVILUR DIVISION

MMGTSY-SL
MAINTENANCE

BENVILUR SUB-DIVISION

MEASUREMENT BOOK

अभिद कुमा ६

M.B.N-1599

२२०.२२००० / ३००२१००

Abstract / cost

12 years maintenance

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1) Restoration / Paint					
62.41m ³ @ V7 m B.P.M. 09					
@ 398.45/m ³ —					26859-
2) Masonry Beam only					
Shoulder					
360.98m ² @ V7 m B.P.M. 10					
@ 54.16/m ² —					19551-
3) Repair / pol holes					
fill with 75 B.M.					
4.22m ³ @ V7 m B.P.M. 10					
@ 9863.07/m ³ —					41647-
4) patch repair over					
pol hole with mix					
local surface					
55.68m ² @ V7 m B.P.M. 11					
@ 211.0/m ² —					11748-
5) masonry C.S. work					
3N @ V7 m B.P.M. 11					
@ 1131.64/Unit —					3395-
					103200-
Less 10%					610320-
					92880-

AD
06-06-2024
21/06/24

Continuation

Madhu
7/6/2024
JAE

