

2016-17

Serial-PT 0067380

BEVIPUR

DIVISION

Makind Commerce

BEVIPUR

SUB-DIVISION

MEASUREMENT BOOK

સામાન કુમાર બાગર

MB No-

1136

સામાન:- MMHSY અન્વયે સંદર્ભ-સોલ્ડ ટ્રાકર
સે-સામાન (સમાવેશ) MMHSY-SC
Schedule XLV-Form No. 134



Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1) Restoration / Patching					
128.13 m ² @ 27 mbs / m ²					2475
@ 4355.32 / m ²					45604
2) Making up / Beams /					
Shoulder stripping					
cross road					
766.78 m ² @ 27 mbs / m ²					26-25
@ 454.01 / m ²					37849
3) Repair / pot hole					
Fully with form					
B.M					
9.35 m ² @ 27 mbs / m ²					26-27
@ 9920.86 / m ²					99760
4) Patch repair over					
pot hole in					
surface Dressing					
125.03 m ² @ 27 mbs / m ²					27
@ 94.86 / m ²					11860
5) Patch repair over					
bituminous surface					
with patch Dressing					
125.88 m ² @ 27 mbs / m ²					28

Continuation

@ 84.83 / m² — 106782
R 198751

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
6/7) Main survey of					
Loop					
IN DV-T-MR-RN-28					
@ 1043.23/een					1043-
7/8) Main survey of					
curves					
IN-DV-T-MR-RN-28					
@ 2165.84/een					2166-
8/12) White washing					
Parade wall					
41.76m ² DV-T-MR-RN-28					
@ 15.36/m ²					6412
					R 2026072
Less 10% below					R 20261-
					R 1823462
30-05-2024					
31/5/2024					
UAE					