

PMGSY Path to Tataru To

Brahm Sched T Ex L Form No. 134

06/500/17-18

प्राप्त

प्राप्त

DIVISION

प्राप्त-2

MANJGACHI

SUB-DIVISION

537

MEASUREMENT BOOK 537

ASHISH YADAV

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(9) cutting of branches of trees & shrubs					240.8
(10) white washing of parapet walls of C.D. works					42.40 MP
Qty. $\Rightarrow$ 2 Nos $\times$ 21.40 MP (9N)					
					$\Rightarrow$ 42.40 MP
Done 30.12.2022 G.S.					
Abstract of cost (4th to Maincebill)					
(1/57) Restoration of rain cuts with soil					77.86 MP
Qty. indep - 390 N.M.B = 77.86 MP					
					@ 355-92/MP = 27676 =
(2/58) Making up of Berms/shoulders stripping excess soil					432.00 MP
Qty. indep - 390 N.M.B = 432.00 MP					
					@ 54-01/MP = 23332 =
(3/59) Repair of pot holes filled with 20 mm B.M.					4.64 MP
Qty. indep - 400 N.M.B = 4.64 MP					
					@ 10614-37/MP = 49251 =

Continuation $\Rightarrow$ 100259-4

C10.

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(4/60) Patch repair precast holes with 20 mm premium carpet & seal coat type-B.				B.F. $\Rightarrow$	100259 =
Qty. in dep - 40 sqm. MB = 61.88 m ²					
				@ 87.05 / m ² =	5387 =
(5/61) Patch repair over bituminous surface with 20 mm premium carpet & seal coat type-B.					
Qty. in dep - 40 sqm. MB = 61.88 m ²					
				@ 75.98 / m ² =	4702 =
(6/62) Maintenance of CD works (HPD)					
Qty. in dep - 40 sqm. MB = 240.5					
				@ 1049.23 / - =	2098 =
(7/63) Maintenance of Rd. Signs					
Qty. in dep - 40 sqm. MB = 1.05 km.					
				@ 1012.11 / km =	1063 =
(8/64) Maintenance of 200 M & 1 km stones					
Qty. in dep - 40 sqm. MB = 1.05 km.					
				@ 576.36 / km =	605 =
(9/65) cutting of branches of trees & shrubs					
Qty. in dep - 41 sqm. MB = 240.9					
				@ 92.64 / - =	195 =

Continuation

$\Rightarrow$ 114309 =

C.O.

1st year	→	40467
2nd year	→	54893
3rd year	→	104465
4th year	→	104465
5th year	→	104465
6th year	→	104465
7th year	→	104465
8th year	→	104465
9th year	→	104465
10th year	→	104465
11th year	→	104465
12th year	→	104465
13th year	→	104465
14th year	→	104465
15th year	→	104465
16th year	→	104465
17th year	→	104465
18th year	→	104465
19th year	→	104465
20th year	→	104465
21st year	→	104465
22nd year	→	104465
23rd year	→	104465
24th year	→	104465
25th year	→	104465
26th year	→	104465
27th year	→	104465
28th year	→	104465
29th year	→	104465
30th year	→	104465
31st year	→	104465
32nd year	→	104465
33rd year	→	104465
34th year	→	104465
35th year	→	104465
36th year	→	104465
37th year	→	104465
38th year	→	104465
39th year	→	104465
40th year	→	104465
41st year	→	104465
42nd year	→	104465
43rd year	→	104465
44th year	→	104465
45th year	→	104465
46th year	→	104465
47th year	→	104465
48th year	→	104465
49th year	→	104465
50th year	→	104465
51st year	→	104465
52nd year	→	104465
53rd year	→	104465
54th year	→	104465
55th year	→	104465
56th year	→	104465
57th year	→	104465
58th year	→	104465
59th year	→	104465
60th year	→	104465
61st year	→	104465
62nd year	→	104465
63rd year	→	104465
64th year	→	104465
65th year	→	104465
66th year	→	104465
67th year	→	104465
68th year	→	104465
69th year	→	104465
70th year	→	104465
71st year	→	104465
72nd year	→	104465
73rd year	→	104465
74th year	→	104465
75th year	→	104465
76th year	→	104465
77th year	→	104465
78th year	→	104465
79th year	→	104465
80th year	→	104465
81st year	→	104465
82nd year	→	104465
83rd year	→	104465
84th year	→	104465
85th year	→	104465
86th year	→	104465
87th year	→	104465
88th year	→	104465
89th year	→	104465
90th year	→	104465
91st year	→	104465
92nd year	→	104465
93rd year	→	104465
94th year	→	104465
95th year	→	104465
96th year	→	104465
97th year	→	104465
98th year	→	104465
99th year	→	104465
100th year	→	104465

[illegible]

Abstract of cost

50

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
01/27/69 Restoration of Rain Cut/ Berms with Soil/Morrum					
Cty vide Page No - 47					
Item No 1017 = 94.65 cum					
@ ₹ 3.55 = 32/cu-m					
					→ ₹ 33688=00
02/7/ Making up of Berms/Shoulder by stripping excess Soil from the Shoulder					
Area vide Page No - 47					
Item No 1027 = 510.00 Sq.m					
@ ₹ 54=01/29 m → ₹ 27545=00					
03/7/ Repair of Pot holes filled with 75mm BM					
Cty vide Page No - 48					
Item No 1031 = 6.50 Cum					
@ ₹ 10614 = 37/Cum					
					→ ₹ 68998=00
04/72/ Patch Repair over Pot holes with 20mm MC with Seal Coat Type B					
Area vide Page No - 48					
Item No (04) = 86.65 Sq.M					
@ ₹ 87=05/Sq.M					
					→ ₹ 7544=00
05/73/ Patch Repair over BT					

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Surface with 20 mm PMC					
Area vide page No. 48					
Item No (05) = 86.81 sq.m					
@ ₹ 75 = 98/89 m					
					→ ₹ 6558 = 00
<u>06/14</u> Maintenance of ED work					
= 04 No					
@ ₹ 1049 = 23 Each					→ ₹ 4197 = 00
<u>07/15</u> Cutting of Branches of trees					
= 02 No					
@ ₹ 97 = 64 Each					→ ₹ 195 = 00
<u>08/16</u> Cutting of shrubs from Roadway					
= 08 No					
@ ₹ 5 = 39 Each					→ ₹ 48 = 00
<u>09/17</u> Forming of grass & weed from the Shoulder.					
Area vide page No. 49					
Item No (08) = 18.00 m ²					
@ ₹ 2 = 00/sqm					→ ₹ 36 = 00
<u>10/18</u> White Washing of Parapet wall of ED work.					
Area vide P-49					
Item No-10 = 62.90 sq.m					

