

Cont of work P.W.D Path Nehra to Ghusi Tak

Schedule XLV-Form No.-134

M.M.G.S.Y (SG)

~~पुणे महानगरपालिका~~

DIVISION

म.म. विभाग कीम वगैरे

खण्ड - 1

Manigachhi

SUB-DIVISION

MEASUREMENT BOOK

579

ASHISH YADAV

Abstract of cost

Sch. XLV Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Restoration of drains with soil					MB
Qty. in dep - 25 of T.M.B = 56.498 m ³					
					② 355-92/m ³ = 20109 =
② Making up of Berms/shoulders stripping excess soil					
Qty. in dep - 25 of T.M.B = 313.875 m ³					
					② 54-01/m ³ = 16952 =
③ Patch repair over pot holes with surface dressing					
Qty. in dep - 25 of T.M.B = 18.75 m ³					
					② 83-18/m ³ = 1635 =
④ Patch repair over bituminous surface with surface dressing					
Qty. in dep - 26 of T.M.B = 18.75 m ³					
					② 26-08/m ³ = 1427 =
⑤ Maintenance of works (H.P.C)					MB
Qty. in dep - 26 of T.M.B = 2 No. 8					
					② 1049-23/each = 2098 =
⑥ Maintenance of Rd. Signs					MB
Qty. in dep - 26 of T.M.B = 0.930 K.M.					
					② 1012-11/K.M = 941 =
⑦ Maintenance of 200 M 2 K.M. Stone					MB
Qty. in dep - 26 of T.M.B = 0.930 K.M.					
					② 571-36/K.M = 531 =

Continuation 543693-00
C.O.

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
				B.F $\Rightarrow$	43693=
⑧ cutting of branches of trees.					
28 trunks				251	
Qty. indep-26 m. MB=1010.					
				297-64/each=98- $\rightarrow$	
⑨ white washing of para net					
walls of CD works				411	
Qty. indep-26 m. MB=42.00 m ²					
				212-38/m ² =646- $\rightarrow$	
				G. Total $\Rightarrow$	44437=
Less 2.20% below average rate 978- $\rightarrow$					
Total value of work done $\Rightarrow$					43459=

30.6.20	37/2020
15.5	A.E.
Materials	15.5
(i) casted Earth $\Rightarrow$	42.40 m ³
(ii) stone chip $\Rightarrow$	1.24 m ³
(iii) Bitumine $\Rightarrow$	80.60 kg
(iv) Benulaton $\Rightarrow$	2.80 kg.

Abstract of Cost

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
01/69 Restoration of Rain cdd/ Berms with Soil/moorm Cety vide P-39 = Item No. 101 = 91.54 m ³ @ ₹ 355 = 92/m ³ — ₹ 2581 = 00					
02/70 Making up of Berms/Shoulder by stripping excess Soil from the Shoulder Area vide P-39 Item No. 102 = 511.00 Sq.m @ ₹ 54 = 01/Sq.m — ₹ 27599 = 00					
03/71 Repair of Pot holes filled With 75mm BM with 20mm Pmc with Seal Coat type Cety vide P-40 Item No. 103 = 57.46 Sq.m Limit = 57.42 Sq.m @ ₹ 87 = 18/Sq.m — ₹ 5006 = 00					
04/72 Repair of Pot holes filled With 75mm BM Cety vide Page No - 40 Item No. 103 = 4.31 m ³ @ ₹ 10631 = 78/m ³ — ₹ 45823 = 00					
05/73 Patch Repair over Pot					

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Pot holes BT Surface with 20mm P.M.C.					
Area vide Page No 40					
Item No (5) = 56.36					
				Sq.m	
@ ₹76 = 08/Sq.m					₹4288.00
06/ Maintenance of CD work					
74 = 0.2 No					
@ ₹1049 = 23 Each					₹2098.00
07/ Cutting of Branches of					
75 trees = 01 No					
@ ₹97 = 01 Each					₹98.00
08/ Cutting of Shrub from					
76 the Road way = 05 No					
@ ₹5 = 99 Each					₹30.00
09/ Forming of grass &					
77 weeds from the Shoulder					
Area vide P-41					
= 13.00 Sq.m					
@ ₹2 = 16/Sq.m					₹28.00
10/ White washing of parapet					
78 wall of CD work					

Continuation