

MMGSY (Gen)

Schedule XLV-Form No. 134

Loss To SAPALD DIVISION

ARTT KUMART SUB-DIVISION

(MAINTENANCE work)

Measurement Book

DOBHI

1965

1

(These four lines should be repeated at the commencement of the measurement relating to each work)

Continuation

Scanned with CamScanner

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
item-⑦	Repair of concrete pavement				
	5	0.9m	0.7m	=	3.15 m ²
	6	0.5m	0.4m	=	1.20 m ²
	4	0.4m	0.3m	=	0.48 m ²
					4.83 m ²
item-⑧	Repair of old joint sealant				
	51	m	3.75	=	191.25 m
item-⑨	Maintenance of C.D works (H-Poles) - 4 H				
item-⑩	Maintenance of C.D works (slab chkl) - 1 H				
item-⑪	Maintenance of Road sign - 1.21 m				
item-⑫	Maintenance of 20m and 1km sign - 1.21 m				
item-⑬	cutting of branches of Tree and shrubs - 3 m				
item-⑭	cutting of shrubs from road way				
	1	600	-	600	
	1	400	-	400	
Continuation					1000 H

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
item (15)	Trimming of grass and weeds white washing of parapet				
	4	3	6.00	0.000	43.20
	2	3	6.00	0.400	14.40
	4	3	6.00	0.000	8.64
④ {	2	1	3.6	0.400	2.88
	4	3	6	0.300	4.32
	2	3	6	0.450	8.24
item (16)	Trimming of grass and weeds				76.68
	2	31	30	1.20	2232
A. Jomay 16/11/23		Shree		16/11/23	
		A. G.			

	ABSTRACT OF COST	
(1/15.1 A)	Restoration of Raincure	
	V.T.M.B.P.No - (1)	
	item (1)	49.75 m ²
	Q ₁	407.70/m ² — 20283.00
(2/15.2 A)	M along top of Bank	
	Shoulder	
	V.T.M.B.P.No - (1)	
	item (2)	281.25 m ²
	Q ₁	60.58/m ² — 17038.00
(3/15.3 A)	Repair of pot holes	
	filled with Jelm	
	V.T.M.B.P.No - (2)	
	item (3)	0.07 m ²

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	Q5	101.5	4.22	/m ³	711.52
(4/15.2.ii) patch repair over					
pod holes with 20mm					
premix concrete					
V.T.M.B.P.No- (2)					
item no (4) —				2238 m ²	
Q5 262.30/m ² —					5870.00
(5/15.3.iii) patch repair over					
Bituminous surface					
V.T.M.B.P.No- (2)					
item no (5) —				23.44 m ²	
B 280.46/m ² —					6574.00
(6/15.3.iii) Filling of cracks					
and joints					
V.T.M.B.P.No- (2)					
item no (6) —				9952	
Q5 4.26/m ² —					4239.00
(7/15.3.iii) Repair of concrete					
pavement					
V.T.M.B.P.No- (3)					
item no (7) —				4.83 m ²	
B 262.30/m ² —					1267.00
(8/15.3.iii) Repair of old road					
scallion					
V.T.M.B.P.No- (3)					
item no (8) —				191.25 m ²	

Continuation

Q5 24.45/m² — 54676.00

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(9/15.20)	Maintenance of road works H.P. culvert				
	V.T.M.B.P.H. (3)				
	item (9) — 4 ft				
	8	1182.79/ft			4731.00 1182.00
(9/15.21)	Maintenance of road works stone culvert				
	V.T.M.B.P.H. (3)				
	item (10) — 1 do				
	8	2426.45/ft			2426.00
(11/15.9)	Maintenance of road sign				

	V.T.M.B.P.H. (9)				
	item (11) — 1.21 m				
	8	1117.04/1m			1352.00
(12/15.11)	Maintenance of road and 10m stone				
	V.T.M.B.P.H. (5)				
	item (12) — 1.2 m				
	8	650.19/1m			787.00
(13/15.12.1)	Culling of branches of tree and shrubs				
	V.T.M.B.P.H. (3)				
	item (13) — 3 ft				
	8	115.57/ft			347.00

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(14/15.12.11) Culling of stalks from road away					
V.T.M.B. P.No. (3)					
item (14) — 1000 H					
@ 7.10/H — 5					7100 =
(15/15.12.11) Trimming of grass and weeds					
V.T.M.B. P.No. (4)					
item (15) — 2232 m ²					
@ 2.37/m ² —					5290 =

(16/15.12) White washing of parapet walls					
V.T.M.B. P.No. (9)					
item (16) — 76.88 m ²					
@ 17.01/m ² —					1308 =
					84005 =
A. K. Nayak 16/11/23 A.C.					
Always 16/11/23 A.C.					

Continuation