

3rd year maintenance

Sch. XLV-Form No. 134 34

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Wk: Maint. of Road from					
To Maheshwar Baitha Ice					
ghar to Hanigan Tole.					
Agency - Md. Ekramul Hoda.					
Agr. No. 41 SBD/2020-21					
D.O.W- 10.06.20					
Actual D.O.C- 05.05.2021					
Date of Entry. 05/04/2021					
Details →					

① Retortation of Raincut -

R.M.S	8 x 2.50 x 1.10 x 0.35 =	7.70
	5 x 2.70 x 0.95 x 0.35 =	4.49
	6 x 2.85 x 1.00 x 0.30 =	1.53

L.M.S	4 x 2.45 x 0.90 x 0.30 =	2.65
	3 x 2.25 x 0.90 x 0.30 =	4.25
	9 x 2.65 x 1.15 x 0.35 =	9.59
		30.21 m ³

② Making of Berms/shoulders -

L.M.S -	4 x 5.00 x 0.85 =	17.00
L.M.S -	6 x 4.50 x 0.90 =	24.30
R.M.S -	5 x 6.00 x 0.95 =	28.50
		69.80 m ²

③ Repair of Pot-holes -

	2 x 2.50 x 1.65 =	8.25
	1 x 2.75 x 1.55 =	4.26

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
② Making up of Berms/shoulders—					
Qty wide THB-P-34					
L-67.50 m ² @ R. 57.36/m ² — R. 3872=					
③ Repair of Pot holes —					
Qty wide THB-P-34					
L-14.06 m ² @ R. 363.53/m ² — R. 511=					
④ Patch Repair over pot holes —					
Qty wide THB-P-35					
L-14.06 m ² @ R. 241.87/m ² — R. 3401=					
⑤ Patch Repair over RT surface —					
Qty wide THB-P-35					
L-14.06 m ² @ R. 258.93/m ² — R. 3641=					
⑥ Maint. of Road Sign —					

Qty wide THB-P-35					
0.07 km @ R. 1077.82/km — R. 75=					
⑦ Road Marking —					
Qty wide THB-P-35					
90.00 m ² @ R. 735.44/m ² — R. 66190=					
⑧ Maint. of already planted trees —					
Qty wide THB-P-35					
10.00 Nos @ R. 574.00/row — R. 5740=					
R. 99695=					
Accl cost + L. cost (13%) @ R. 12960=					
Accl S. Fee (10%) — R. 266=					
R. 112921=					
Less (0.25%) Below — R. 282=					
R. 112639=					