

ਕਿਸਾਨੀ ਖੇਤਰਾਂ ਵਿੱਚ (ਕਿਸਾਨੀ) ਟੋਟ ਹੋਣ
1000000 ਪੜ੍ਹਿਚਮ ਹੋਣ

Schedule XLV Form No. 134.

R. W. D. ਕੇਜੀ ਪਟੀ DIVISION

R. W. D. ਕਿਸਾਨੀ SUB-DIVISION

KLIPPA LAKSHMI

Measurement Book

M. B. No. - 1084

Abstract of Cost

(1) Restoration of Reinforced

Vide T.M.B., Item-1, P-35

$$= 76.20 \text{ m}^3$$

(2) Mould of Shoulders

$\frac{\text{Vide}}{\text{T.M.B.}}$, Item-2, P-35 = 393.05 m²

(3) P/L - 75 mm. B.M.

$\frac{\text{Vide}}{\text{T.M.B.}}$, Item-3, P-35/36

$$= 5.67 \text{ m}^3$$

(4) Patch Repair of Pav
H/Ws

$\frac{\text{Vide}}{\text{T.M.B.}}$, Item-4, P-36 = 75.59 m²

Continuation

Sch. XLV-Form No. 134

[illegible]

Continuation

Executive Engineer
R.W.D. Works Division
Banspatti