

ಮುಖ್ಯ  
SOS8 ಸುರಕ್ಷತಾ ವರ್ಗ  
Schedule XLV-Form No.-134  
ಮುಖ್ಯ (59)-17-18

ಅಧ್ಯಕ್ಷ  
DIVISION

ಅಧ್ಯಕ್ಷ  
SUB-DIVISION

**MEASUREMENT BOOK**

SOS8 to Jaiderpatti Brahmanthola.

4512/3511C 745

995

| Particulars                                   | Details of actual measurement |    |    |    | Contents of area |
|-----------------------------------------------|-------------------------------|----|----|----|------------------|
|                                               | No.                           | L. | B. | D. |                  |
| Measure of work. Main stone of road from 3052 |                               |    |    |    |                  |
| Jairav path to Braham mola.                   |                               |    |    |    |                  |
| Agency: Sanjay Kymor. Jha.                    |                               |    |    |    |                  |
| Agout 45.5.2/2018-19                          |                               |    |    |    |                  |
| Date of Cam. 09/3/2019                        |                               |    |    |    |                  |
| Date of Cam 08/3/2020                         |                               |    |    |    |                  |
| Date of Cam. 22/2/2021                        |                               |    |    |    |                  |
| 3rd y- 23/2/2023                              |                               |    |    |    |                  |

Measurement of area

(1) Restoration of road with. Cail.

|     |       |       |       |         |
|-----|-------|-------|-------|---------|
| 5x  | 6.00x | 1.10x | 0.30  | = 9.90  |
| 6x  | 7.00x | 1.00x | 0.30  | = 12.60 |
| 8x  | 7.50x | 0.90x | 0.30  | = 9.72  |
| 10x | 3.50x | 1.10x | 0.30  | = 11.55 |
| 12x | 6.00x | 0.90x | 0.30  | = 19.44 |
| 20x | 3.50x | 1.20x | 0.30  | = 25.20 |
| 5x  | 7.50x | 1.00x | 0.30  | = 11.25 |
| 11x | 3.00x | 1.10x | 0.30  | = 10.89 |
|     |       |       | Total | 110.55  |

(2) Making up of Broom's hub  
shopper do

|     |        |      |          |
|-----|--------|------|----------|
| 10x | 10.00x | 0.90 | = 90.00  |
| 5x  | 11.00x | 1.00 | = 55.00  |
| 6x  | 15.00x | 0.90 | = 81.00  |
| 7x  | 20.00x | 0.80 | = 112.00 |
| 11x | 30.00x | 0.60 | = 198.00 |
| 7x  | 15.00x | 0.90 | = 94.50  |

Continuation

630.50  
624.00

CC

2023

Tre  
DD  
Bar  
Bill

to

20  
wo

# ABSTRACT OF PLASTING

54

Sch. XLV-Form No. 134

| Particulars                            | Details of actual measurement |    |    |    | Contents of area      |
|----------------------------------------|-------------------------------|----|----|----|-----------------------|
|                                        | No.                           | L. | B. | D. |                       |
| ① Rotational of rainfall               |                               |    |    |    |                       |
| cut. side                              | —                             | —  | —  | —  |                       |
| wide T.M. p.p.e. (53) 2h (1)           |                               |    |    |    |                       |
| 110.55 M <sup>2</sup> @ R. 390.29/-    |                               |    |    |    | B 4314720             |
| ②. Making up of Bony/sab               |                               |    |    |    |                       |
| do                                     | —                             | —  | —  | —  |                       |
| wide T.M. p.p.e. (53) 2h (2)           |                               |    |    |    |                       |
| 624.00 M <sup>2</sup> @ R. 52.17/-     |                               |    |    |    | B 325542              |
| ③. Repair of pot hole cut              |                               |    |    |    |                       |
| 75 mm thick                            | —                             | —  | —  | —  |                       |
| wide T.M. p.p.e. (53) 2h (3)           |                               |    |    |    |                       |
| 3.20 M <sup>2</sup> @ R. 10822.62/-    |                               |    |    |    | B 3463220             |
| ④. patch repair of pot hole            |                               |    |    |    |                       |
| do                                     | —                             | —  | —  | —  |                       |
| wide T.M. p.p.e. (53) 2h (4)           |                               |    |    |    |                       |
| 42.68 M <sup>2</sup> @ R. 225.59/-     |                               |    |    |    | B 962820              |
| ⑤. Main hole of C.D. wall              |                               |    |    |    |                       |
| wide T.M. p.p.e. (53) 2h (5)           |                               |    |    |    |                       |
| 3 M <sup>2</sup> @ R. 1131.64/-        |                               |    |    |    | B 339520              |
| ⑥. whole washing of C.D. wall          |                               |    |    |    |                       |
| do                                     | —                             | —  | —  | —  |                       |
| wide T.M. p.p.e. (53) 2h (6)           |                               |    |    |    |                       |
| 62.40 M <sup>2</sup> @ R. 15.08/-      |                               |    |    |    | B 94120               |
|                                        |                               |    |    |    | 70th R. 12499720      |
| less 100% below                        |                               |    |    |    | (-) 1243020           |
|                                        |                               |    |    |    | B 11186720            |
| total                                  |                               |    |    |    |                       |
| (1) cut. side                          |                               |    |    |    | 110.55 M <sup>2</sup> |
| (2). Rotational of 4.57 M <sup>2</sup> |                               |    |    |    |                       |
| (3) st. c.c. p.p.e.                    |                               |    |    |    | Confidential          |
| (4) Rohe                               |                               |    |    |    | 0.335 M <sup>2</sup>  |

20

payr

Trea

DDC

Ban

Bill

to

to

to

to

to

to

to

to

to

to

to

to

to

to



4th year Ruler's residence

Sch. XLV-Form No. 134

| Particulars                                                   | Details of actual measurement |    |    |    | Contents of area |
|---------------------------------------------------------------|-------------------------------|----|----|----|------------------|
|                                                               | No.                           | L. | B. | D. |                  |
| Measure of area. Main land of road from 5056 to Boradhamatola |                               |    |    |    |                  |
| Agency. Sanjay Kumar The                                      |                               |    |    |    |                  |
| Agree. 45 S.K.D/2019-20                                       |                               |    |    |    |                  |
| Date of Comm. 9/3/2019                                        |                               |    |    |    |                  |
| Date of Comm. 08/3/2020                                       |                               |    |    |    |                  |
| Actual date of Comm. 22/2/2020                                |                               |    |    |    |                  |
| 4th year 23/2/2024                                            |                               |    |    |    |                  |

Measurement given

(1) Restoration from front of road

Side -

5x 11.10x 1.10x 0.30 = 16.50m<sup>2</sup>

|     |          |       |      |         |
|-----|----------|-------|------|---------|
| 6x  | 8.00x    | 1.10x | 0.30 | = 15.84 |
| 7x  | 6.00x    | 0.90x | 0.30 | = 11.34 |
| 8x  | 6.50x    | 1.10x | 0.30 | = 17.16 |
| 2x  | 5x 5.00x | 1.10x | 0.30 | = 25.01 |
| 2x  | 7.00x    | 0.90x | 0.30 | = 23.12 |
| 10x | 6.50x    | 1.20x | 0.30 | = 23.40 |
| 6x  | 8.50x    | 1.10x | 0.30 | = 17.02 |

Total 131.38

128.39

(2) Making up of Berms/Shoulder

do

|     |        |      |   |                      |
|-----|--------|------|---|----------------------|
| 10x | 15.00x | 1.00 | 2 | 150.00m <sup>2</sup> |
| 12x | 12.00x | 1.10 | 2 | 158.40               |
| 15x | 15.00x | 1.00 | 2 | 225.00               |
| 12x | 15.00x | 1.00 | 2 | 180.00               |

Continuation

713.40

713.35



| Particulars                                           | Details of actual measurement |    |    |    | Contents of area |
|-------------------------------------------------------|-------------------------------|----|----|----|------------------|
|                                                       | No.                           | L. | B. | D. |                  |
| (1) Retros. Lion of garden<br>cut acc. to - a - a - a |                               |    |    |    |                  |
| width 4.11 m (55) 22 (1)                              |                               |    |    |    |                  |
| 128.39 M <sup>2</sup> @ R. 390.39/- R.                |                               |    |    |    | 5010920          |
| (2) Working up of Bench/seat<br>do - a - a - a        |                               |    |    |    |                  |
| width 4.11 m (55) 22 (2)                              |                               |    |    |    |                  |
| 713.35 M <sup>2</sup> @ R. 52.17/- R.                 |                               |    |    |    | 3721020          |
| (3) Repair of Path/roadway<br>do - a - a - a          |                               |    |    |    |                  |
| width 4.11 m (56) 22 (1)                              |                               |    |    |    |                  |
| 4.21 M <sup>2</sup> @ R. 10822.62/- R.                |                               |    |    |    | 4556320          |
| (4) Repair of Path/road<br>cut acc. to do - a - a - a |                               |    |    |    |                  |
| width 4.11 m (56) 22 (2)                              |                               |    |    |    |                  |
| 56.13 M <sup>2</sup> @ R. 225.59/- R.                 |                               |    |    |    | 1266220          |
| (5) Re-lime washing of path<br>do - a - a - a         |                               |    |    |    |                  |
| width 4.11 m (56) 22 (7)                              |                               |    |    |    |                  |
| 63.00 M <sup>2</sup> @ R. 15.98/- R.                  |                               |    |    |    | 100720           |
|                                                       |                               |    |    |    | T.R. 14655120    |
| Less 10% below (H) R.                                 |                               |    |    |    | 1465520          |
|                                                       |                               |    |    |    | R 13189620       |
| Pathway -                                             |                               |    |    |    |                  |
| (1) Soil - 128.39 M <sup>2</sup>                      |                               |    |    |    |                  |
| (2) Gravel - 5.94 M <sup>2</sup>                      |                               |    |    |    |                  |
| (4) St. Clay - 1.52 M <sup>2</sup>                    |                               |    |    |    |                  |
| (5) Bch. - 0.4335 M <sup>2</sup>                      |                               |    |    |    |                  |

Continuation

05/6/23