

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(1) <u>Trimming of grass & weeds</u>					961.00 m ²
<u>Survey</u>					
<u>01/04/24</u>					
<u>J.E.</u>					
<u>Abstract of cost</u>					
(1/1) <u>Restoration of raincurb</u>					
130.29 m ³ qty vide TMBP (63)					
item (1) @ Rs. 365.24/m ³ - Rs. 47,587.20					
(2/2) <u>Making up of Berms/shoulder</u>					
639.67 m ² qty vide TMBP (64)					
item (2) @ Rs. 54.16/m ² - Rs. 34,645.00					
(3/3) <u>Repair of pot holes with</u>					
<u>75 mm BM</u>					
7.613 m ² qty vide TMBP (64)					
item (3) @ Rs. 11465.77/m ² - Rs. 87,289.00					
(4/4) <u>Patch repair over pot</u>					
<u>holes with 20 mm premix</u>					
101.507 m ² qty vide TMBP (64)					
item (4) @ Rs. 218.58/m ² - Rs. 22,198.00					
(5/5) <u>Patch repair on bituminous surface with premium</u>					
101.507 m ² qty vide TMBP (64)					
item (5) @ Rs. 306.62/m ² - Rs. 31,124.00					
(6) <u>P/L of hot applied thermoplastic compound</u>					
240.00 m ² qty vide TMBP (64)					
item (6) @ Rs. 867.77/m ² - Rs. 2,08,265.00					
(7) <u>Maint of Pot signs</u>					

Continuation

[illegible]