

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	ABSTRACT OF COST				
	3rd year maintenance Beel.				
CH $\Rightarrow$	M M M S Y (UEN)				
Name of Work $\Rightarrow$	Gaura to Hath Keshri Cha Tola				
Agency $\Rightarrow$	Sri Shailendra Kr Tiwari				
Date of Entry $\Rightarrow$	7.12.23				
	Payment made to Agency for				
	following item of work				
Item No $\frac{1}{1}$	restoration of raiment -				
TMB Page (73) $\Rightarrow$	70.88 m ³				
	ch	380 = 58/m ³		h	26976 = 0
Item No $\frac{2}{2}$	making up berm/shade				
TMB Page (73) $\Rightarrow$	337.50 m ²				
	ch	58.60/m ²		h	19778 = 0
Item No $\frac{3}{3}$	Pot repair m 75 mm Bm				
TMB Page (73) $\Rightarrow$	4.48 m ³				
	ch	11569 = 52/m ³		h	51831 = 0
Item No $\frac{4}{4}$	Patch repair on Pot hole filled				
TMB Page (73) $\Rightarrow$	59.77 m ²				
	ch	313 = 54/m ²		h	18740 = 0
Item No $\frac{5}{5}$	Patch repair on Bt Bm				
TMB Page (73) $\Rightarrow$	59.77 m ²				
	ch	332 = 31/m ²		h	19862 = 0
Item No $\frac{6}{7}$	maintenance of CD Hump				
TMB Page (73) $\Rightarrow$	2.00 m				
	ch	1117 = 0/each		h	2234 = 0
Item No $\frac{7}{9}$	maintenance of road segn				
TMB Page (73) $\Rightarrow$	0.15 km				
	ch	1074 = 51/km		h	161 = 0

Continuation

Continuation