

30 days Maintenance Bill

75

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - Ramgarh Pas Bething Road to Kalani Yadav tola					
Agenda No - SBD 126/ 2019-20					
Agency - Sri Shalendra Kumar Bhowmik					
		Work done			
① Restoration of drain cut - do do -					
		30.00 x 0.80 x 0.30 =			7.20 M ³
		30.00 x 1.00 x 0.30 =			9.00
		30.00 x 1.00 x 0.30 =			9.00
		116 x 1.10 x 0.60 x 0.30 =			22.96
		48 x 1.90 x 0.60 x 0.30 =			16.42
		42 x 2.00 x 0.60 x 0.30 =			15.12
		63 x 1.50 x 0.60 x 0.30 =			17.01

		57 x 1.30 x 0.50 x 0.30 =			11.59
		90 x 0.90 x 0.40 x 0.25 =			8.10
		80 x 1.30 x 0.50 x 0.30 =			17.36
		143 x 1.00 x 0.40 x 0.30 =			17.16
		92 x 1.20 x 0.60 x 0.30 =			19.87
		116 x 1.10 x 0.60 x 0.30 =			22.96
					197.55 M ³

② Making up - beams - and chun -					
		18 x 3.00 x 1 =			45.00 M ²
		10 x 30.00 x 1.00 =			300.00
		10 x 30.00 x 1.00 =			300.00
		10 x 30.00 x 1.00 =			300.00
					945.00 M ²

③ Repairing pot hole - do -					
		10 x 5.00 x 1.00 x 0.075 =			3.75 M ³
		30 x 4.50 x 1.00 x 0.075 =			6.75 M ³

Continuation

10 x 2.15 x 1.00 x 0.075 = 1.61 M³

12.11 M³

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Abstract of cost					
— x —					
① Restoration of main cut — do —					
vide T.M.B. P-75					
at 198.45 m ³					
CR 380 = 50/m ³				R	75526 = w
② Melting up Berms — shall — do —					
vide T.M.B. P-75					
at 945 = 10 m ²					
CR 58 = 60/m ²				R	55377 = w
③ Repair of Pot hole — do — do —					
vide T.M.B. P-75					
at 12-11 m ³					
CR 11465 = 28/m ³				R	139061 = w
④ Patch & repair over pot holes					
do vide T.M.B. P-76					
at 161 = 72 m ²					
CR 311 = 12/m ²				R	50314 = w
⑤ Patch & repair over bituminous surface — do —					
vide T.M.B. P-76					
at 161.22 m ²					
CR 330 = 05/m ²				R	53375 = w
⑥ Maintenance of D.W.U. — do —					
vide T.M.B. P-76					
at 4.00 m ²					
CR 1117 = w/Ann				R	4468 = w

Continuation

