

# 5th year Maintenance Bill

57

Sch. XLV-Form No. 134

| Particulars                        | Details of actual measurement |    |    |    | Contents of area |
|------------------------------------|-------------------------------|----|----|----|------------------|
|                                    | No.                           | L. | B. | D. |                  |
| <del>Abstract of cost</del>        |                               |    |    |    |                  |
| (1) Restoration of Rain cote.      |                               |    |    |    |                  |
| 284.53 sq ft Qty vide p.No. 84     |                               |    |    |    |                  |
| Rs 317.12/-                        |                               |    |    |    | Rs 80,716.00     |
| (2) Maintenance of Rooster         |                               |    |    |    |                  |
| Shoulder                           |                               |    |    |    |                  |
| 1457.00 sq ft Qty vide p.No. 85    |                               |    |    |    |                  |
| Rs 50.35/-                         |                               |    |    |    | Rs 71,345.00     |
| (3) Maintenance of bituminous      |                               |    |    |    |                  |
| Surface.                           |                               |    |    |    |                  |
| 292.99 sq ft Qty vide p.No. 85     |                               |    |    |    |                  |
| Rs 364.19/-                        |                               |    |    |    | Rs 1,06,703.00   |
| (4) The Maintenance of WBM Road    |                               |    |    |    |                  |
| including filling up to 2 ft.      |                               |    |    |    |                  |
| 292.99 sq ft Qty vide p.No. 85     |                               |    |    |    |                  |
| Rs 364.19/-                        |                               |    |    |    | Rs 1,06,703.00   |
| (5) Patch repair on already filled |                               |    |    |    |                  |
| gap holes with WBM in 1:3 ratio    |                               |    |    |    |                  |
| 2044 sq ft Qty vide p.No. 85       |                               |    |    |    |                  |
| Rs 313.15/-                        |                               |    |    |    | Rs 9,17,444.00   |

Continuation

Scanned with CamScanner