

701 To PUNHAD HARIJAN TOLA

Schedule XLV-Form No. 134

BEWIPUR

MMHSY-SC
(Maintenance)
DIVISION

STHANSHYAMPUR SUB-DIVISION

Measurement Book

21441503A

M.B.No- 1395

(22422414 Maintenance)

ABSTRACT OF COSTING

6

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Repairs of drain after soil: 2					
width M. 1.10 (1) 2d (1)					
62.88 M ² @ R. 355.92/- B					2238020
② Making of Dorrion / Skuta do - a - a - a					
width M. 1.10 (1) 2d (2)					
349.31 M ² @ R. 54.01/- B					1886620
③ Rate repair of 75 mm tile - a - a - a					
width M. 1.10 (1) 2d (3)					
25.08 M ² @ R. 97.72/- B					245120
④ Rate repair of 150 mm cuff - a - a - a					
width M. 1.10 (1) 2d (4)					
25.08 M ² @ R. 87.16/- B					218620
⑤ Making of H.P. out do - a - a - a					
width M. 1.10 (1) 2d (5)					
2 M ² @ B 1049.23/- B					209820
⑥ Making of Roof 200 mm width M. 1.10 (1) 2d (6)					
1.04 M ² @ B 1012.11/- B					105320
⑦ Making of 200 mm width M. 1.10 (1) 2d (7)					
1.04 M ² @ B 971.36/- B					59420
⑧ whitewashing of roof width M. 1.10 (1) 2d (8)					
42.00 M ² @ B 15.36/- B					64520
					50273200

Scanned with OKEN Scanner