

✓
World Bank

M.B.S.LNO-251

Schedule XLV-Form No.-134

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, मधोरा

DIVISION

SUB-DIVISION

TARAIYA
बेलही PMDSY से फरीदपुर पुरानी व/जा 12 नं०

MEASUREMENT BOOK

राजकुमार सिंह

5th year Maintenance Bill

80

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - Maintenance of Road from Belhara Newari PMGSY to Faridnagar Purani Bazar Tak.					
Agency - Rajkumar Singh.					
Agreement No - 07/SBD/16-17					
Actual dt of completion - 28.03.2019.					
RECORD ENTRY					
(1) Restoration of Road cuts - do - do - H/S.					

$$2 \times 6.80 \times 1.80 \times 0.300 = 21.22 \text{ m}^3$$

$$9 \times 4.80 \times 1.20 \times 0.300 = 15.55 \text{ m}^3$$

$$6 \times 5.00 \times 1.30 \times 0.300 = 11.70 \text{ m}^3$$

$$12 \times 9.50 \times 1.30 \times 0.300 = 44.46 \text{ m}^3$$

$$7 \times 10.00 \times 1.25 \times 0.300 = 26.25 \text{ m}^3$$

$$8 \times 12.00 \times 1.30 \times 0.300 = 37.44 \text{ m}^3$$

$$5 \times 5.50 \times 1.25 \times 0.300 = 10.31 \text{ m}^3$$

$$4 \times 15.00 \times 1.30 \times 0.300 = 23.40 \text{ m}^3$$

$$7 \times 10.00 \times 1.30 \times 0.300 = 27.30 \text{ m}^3$$

$$6 \times 4.50 \times 1.20 \times 0.300 = 9.72 \text{ m}^3$$

$$1 \times 5.50 \times 1.10 \times 0.300 = 1.82 \text{ m}^3$$

$$1 \times 2.00 \times 1.20 \times 0.300 = 0.60 \text{ m}^3$$

$$\text{Qty} - 229.77 \text{ m}^3$$

(2) Maintenance of another shoulders - do - do - H/S.

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① White washing on Parapet — do — do — 7/5					126.00m ²

~~24-4-24~~
A-E

26/03/24
J.E

ABSTRACT OF COST

① Restoration of Rails
Cuts — do — do — 7/5

~~23977m²~~ (V.T.M.B.P. No-80)

① Rs. 318.07/m² — Rs. 73083=00

② Maintenance of another
Shoulders — do — do — 7/5

1276.03m² (V.T.M.B.P. No-81)

① Rs. 48.62/m² — Rs. 62041=00

③ Patch Repair Filled
with 75mm Bm — do —
do — as per 7/5

14.125
187.58m² (V.T.M.B.P. No-82)

① Rs. 94.24/m² — Rs. 17678=00

14/11/2000

④
⑤ Patch Repair over Bitumin
holes — do — do — 7/5

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
187.58 m ² (V.T.M.B.P. No-82)					
① 78.90.03/m ² - 78.16888200					

⑤ Maintenance of HPC -
do do - 7/5.

6 Nos (V.T.M.B.P. No-82)

② 912.51/No - 78.5475200

⑥ maintenance of slab

Culverts do do - 7/5.

4 Nos (V.T.M.B.P. No-82)

③ 18.190236/No - 78.7609200

⑦ Cutting of Branches of
Trees do do - 7/5.

4 Nos (V.T.M.B.P. No-82)

④ 78.81.27/No - 78.325200

⑧ White Washing of
Parapet do do - 7/5.

126.00 m² (V.T.M.B.P. No-82)

⑤ 78.13.42/m² - 78.1691200

⑨ Pot holes over pot
holes do do - 7/5.

187.58 m² (V.T.M.B.P. No-82)

⑥ 78.94.24/m² - 78.17678200

78.325901200

less 4.75% as per order - 78.15480200

78.310491200

Continuation
24-4-21
A.C.

6884
26/03/24
J.E.