

MMGSY (World Bank) Packag No - MMGSY -
WB-19 Darbhanga-2-02
Schedule XLV-Form No. 134

Executive Engineer

R. W. D. (W) Division

Darbhanga-2

(World Bank)

DIVISION

Mansbachhi

SUB-DIVISION

Measurement Book

Sri Vivek Thg.

No. 796

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>Abstract of Cost</u>					
01 39	Restoration of Rain cistern with Soil/Masonry				
				Qty vide P-50	
Item No. 01 39				= 88.80 cum	
				@ ₹ 422=00/cum	₹ 37474=00
02 55	making up of Berms/ Shoulder by stripping Excess Soil from the Shoulder				
				Area vide P-51 = 490.80 sqm	
				@ ₹ 57=30/sqm	₹ 28123=00
03 56	Repair of pot holes with 75 mm BM				
				Qty vide P-51 = 3.45 cum	
				@ ₹ 11089=00/cum	₹ 38257=
04 57	Patch Repair over pot holes with mass				
				= 46.76 sqm	
				@ ₹ 285=00/sqm	₹ 13327=00
05 62	Trimming of Grass				

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Waste from the Shoulder					
Vide - Page No - 52					
					= 16.00 Sqm
@ ₹ 2 = 89 / Sqm					→ ₹ 16 = 00
White washing of parapet wall of CD work.					
Vide - P-52 =					82.56 Sqm
@ ₹ 17 = 0 / Sqm					→ ₹ 1404 = 00
					→ ₹ 118631 = 02
Add GST @ 12% →					14236 = 00
Add L.C @ 1% →					1186 = 00
					→ ₹ 134053 = 00
Raw					
02-05-21					
56					
Work					
15/94					

Continuation