

KINGS - To 3 to Madhavan-1020 Km
SC

Schedule XII-Form No. 134

Ag. No. 49 S&D:- 2020-2021

Shenghafi

DIVISION

Gurua

SUB-DIVISION

Ranjana Yadav

MEASUREMENT BOOK

1286

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1st year maintenance					
of					
N/W					
To 3 to Nadiawan					
(Nmbay S.C.)					
Agency - Ramjatan yadav.					
Agreement No. 49/SB/2020-21					
date of Agmt. 30.6.2020					
date of completion 29.6.2021					
Actual date of completion 28.6.2021					
below 0.01%					
date of entry					

Estimate of area					
brought with Soil Mooring					
2 x	5.20 x	0.70 x	0.30 =	2.808 m ²	
3 x	2.80 x	0.80 x	0.30 =	2.718 m ²	
4 x	1.20 x	0.90 x	0.30 =	1.296 m ²	
5 x	4.20 x	0.70 x	0.30 =	4.41 m ²	
2 x	1.80 x	0.90 x	0.30 =	0.972 m ²	
4 x	1.20 x	0.80 x	0.30 =	1.152 m ²	
3 x	1.40 x	0.90 x	0.30 =	1.134 m ²	
7 x	1.10 x	0.90 x	0.30 =	2.079 m ²	
6 x	1.30 x	0.80 x	0.30 =	1.872 m ²	
2 x	9 x	0.70 x	0.30 =	3.78 m ²	
13 x	1.20 x	0.90 x	0.30 =	4.32 m ²	
18 x	1.40 x	0.80 x	0.30 =	6.048 m ²	
				27.885 m ²	
				Remains 26.58 m ²	

Continuation

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
					Abstract of cost.
(1/15.1.0)	Restoration of rainwater bricks along				
	Qty vide T.M.B.P. 71				
	item no 1				
26.58 m ³	(2)	386.14/m ³	10264		
(2/15.2.01)	Making of brick shoulders - also				
	Qty vide T.M.B.P. 74				
	item no 2				
147.66 m ²	(3)	57.36/m ²	84702		
(3/15.3.01)	Repair of pot holes filled with 75mm				
	W.B.M. - also				
0.04 m ³	(4)	9423.90/m ³	3772		
(4/15.3.11)	patch repair over Bitumens surface with 20mm priming Carpet - also				
	Qty vide T.M.B.P. 72				
	item no 4				
12.3 m ²	(5)	243.84/m ²	2999		
(5/15.3.11)	patch repair over Bitumens surface - also				
	Qty vide T.M.B.P. 73				
	item no. 5				
12.3 m ²	(6)	260.96/m ²	32102		

T-25320

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(6) RD 706			Bl. 025 2		2532-00
			Creek Sealing		
			filling of Creek - a-b		
			Qty vide Tmp 73		
			item no 6		
			525 m @ 3.96/m	15	2079.5
(7) Om 107			Repair of concrete		
			Permet. Sealing chisels		
			Qty vide Tmp 73		
			item no 7		
			11.6 m ² @ 243.84/m ²	15	2829.2
(8) RD 1015			Repair of joint		
			Sealing of joint		
			Qty vide Tmp 73		
			item no 8		
			464.07 m @ 23.48/m	15	10896
(9) (15.7.11)			Maintenance of CD work		
			also QTY vide		
			Tmp 73 item no 9		
			02 Nos @ 1130.67/each	15	2261.4
(10) (15.7.11)			Repair of CD/road culvert		
			QTY vide Tmp 73		
			item no 10		
			01 Nos @ 2329.21/each	15	2329.5

T = 45714

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1					Bf Rs = 45714/-
(11/75.9)					Maintenance of Road
					Left hand side of road
					dry side trap no 73
					item no 11
1.02 km					@ 1077.81/km Rs: 1099-
(12/15.11)					Maintenance of 200m
					& km stone road
					dry side trap no 74
					item no 12
1.02 km					@ 628.12/km Rs: 641-
(13/15.12)					Cutting of shrub from
					road
					dry side trap no 75
					item no 12
525 m					@ 6.73 each Rs: 2648-
(13/15.13)					White washing of
					parapet of CD delo
					dry side trap no 74
					item no 13
14.76 m ²					@ 16.21/m ² Rs: 239-
					50341
Less As per Agreement below					5
0.01%					Total Rs: 50336-
(N/A)					
18/10/2023					
18/10/2023					

Continuation