

Particulars	Details of actual measurement			Contents of area
	No.	L	B	
Year year maintenance work				
Name of work -	Maintenance of drain from Terasi Nahel per			
	Tetrascon Nahel per			
	Loatan Tala to Gorniya			
Agency -	Eni Ashok Kumar			
Agreement No.	332-55/2018-19			
Date of work completed -	18/02/19			
Actual date of completion -	14/02/22			
Date of entry -	15/2/24			
(1) Restoration of Repair	ceiling 800 x 1100 mm			
	16x	6.0Mx	1.10x	0.310 = 31.68M ³
	19x	5.0Mx	1.0Mx	0.310 = 28.50M ³
	15x	5.0Mx	1.10x	0.310 = 24.75M ³
	4x	2.0Mx	0.90x	0.310 = 2.16M ³
				Total: 87.50M ³
(2) Maintenance of earthen shoulder				
	16x	6.0Mx	1.10	= 105.60ML
	18x	5.0Mx	1.0M	= 90.00ML
	17x	8.0Mx	1.20M	= 163.20ML
	14x	6.0Mx	0.90	= 75.60ML
	16x	5.0Mx	1.0M	= 80.00ML
				Total: 514.4ML
(3) Repair of pot holes				
	cut 75MM in clay			

Continuation
complete 75

1

49
Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	11x	3.90x	1.10x	0.02x	3.93m ²
	5x	2.00x	1.00x	0.02x	0.25m ²
	4x	2.00x	1.10x	0.02x	0.66m ²
				total	4.94m ²
④	patch repair of 1st floor				
	holes 11x17, 13.2mm 100.05				
	1mm Min Seal 86.25sq				
	15x	2.00x	1.50x	-	45.00m ²
	1x	5.00x	1.00x	-	5.00m ²
	8x	3.00x	1.00x	-	24.00m ²
				total	74.00m ²
⑤	patch repair of 1st floor				
	Area same as ④				
					74.00m ²
⑥	Maintenance of HP ceiling				
	quantity				02 NO
⑦	Maintenance of 8th ceiling				
	quantity				01 NO
⑧	Maintenance of 8th floor				
					1/34x
⑨	Maintenance of 8th floor				
					1/34x
⑩	ceiling & Banding floor				
	8.5/24x				02 NO
⑪	white washing of plaster				
	work done				42.00m ²
				Self	
				16/02/24	
				AGS 265	

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>ABSTRACT OF WORK</u>					
① Restoration of Rain cell					
Width THS. ps	(48) ely (1)				
Quantity =	87.30 M ²		362.28 M ³		31699 = 10
② Maintenance of earthen shoe box in cul					
Width THS. ps	(48) ely (2)				
Quantity =	514.4 M ²		53.70 M ²		27623 = 10
③ Repaired pot-holes					
Width THS. ps	(48) ely (3)				
Quantity =	4.94 M ²		9372	61/M ²	46300 = 10
④ Patch repair over pot					
Width THS. ps	(49) ely (4)				
Quantity =	74.0 M ²		196.70 M ²		14556 = 10
⑤ Patch repair over brickwork surface in cul					
Width THS. ps	(49) ely (5)				
Quantity =	74.0 M ²				
⑥ Maintenance of Heron pits culvert in cul					
Width THS. ps	(49) ely (6)				
Quantity =	02 NO		1120.20/each		2244 = 10
⑦ Maintenance of glass culvert					
Width THS. ps	(49) ely (7)				
Quantity =	01 NO				
			2317.50/each		23172 = 10

Continuation Page 10 12466620

Continuation Total 1246662 = 10

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(8) Maintenance of road (8) m wide TMS. per 49 ch. 8				3.1	124666 =
Quantity: 1.13 km					
(9) Maintenance of 240 m KM stone				1028 = 63/km	1218 =
Quantity: 1.13 km					
(10) Maintenance of 596 = 09/km					673 =
Quantity: 1.13 km					
(11) 02 More 106 = 59/each					213 =
Quantity: 42.0 m					
(12) 16 = 36/m					686 =
Quantity: 42.0 m					
Total					127456 =
Less 10% ASP Agreement					12745 =
Total					114711 =
16/2/24					
AGA 25					
Material Statement					
(I) stone clips				2.44 m	
(II) E19				8730 m	
(III) E19				5144 m	
(IV) 120 m				0.1406 m	
16/2/24					
AGA 56					

Continuation