

Sath line service canal Pmlsy Road do

Koeriyā mahadalit Tota

Shedule XLV Form No. 134.

mmlsy/scj

Bikram, qam, T

DIVISION

Dinaga

SUB-DIVISION

Measurement Book

566

Sanyay Kumar

2nd Year Maintenance

32

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work -	Suth Line Service				
	PMUTSY Road To Koin'za				
	Mahadalit Tola				
Agency -	Sanjay Kumar				
Appr. No -	055 B/D/2019-2020				
Date of start -	05/07/2019				
Date of Compl -	04/07/2020				
✓ Restoration of Rain					
Cyt of Soil -					
1	X 1.5	X 0.75	X 0.30	= 0.337	
1	X 0.90	X 0.70	X 0.30	= 0.189	
1	X 1.10	X 0.80	X 0.30	= 0.261	
1	X 1.80	X 0.75	X 0.30	= 0.405m	
2	X 1.30	X 0.90	X 0.30	= 0.702m ³	
2	X 1.30	X 0.90	X 0.30	= 0.702	
2	X 1.50	X 0.90	X 0.25	= 0.675	
2	X 1.50	X 0.90	X 0.25	= 0.675	
3	X 1.50	X 0.85	X 0.30	= 1.147	
4	X 1.60	X 0.90	X 0.28	= 1.60	
4	X 1.70	X 0.83	X 0.30	= 1.693m ³	
3	X 1.90	X 0.80	X 0.30	= 1.592	
5	X 1.80	X 0.85	X 0.30	= 2.295	
5	X 1.80	X 0.85	X 0.30	= 2.295	
4	X 1.85	X 0.68	X 0.30	= 1.50	
4	X 1.60	X 0.90	X 0.29	= 1.67	
4	X 1.60	X 0.80	X 0.30	= 1.536	

Continuation

$$4 \times 1.60 \times 0.80 \times 0.30 = 1.536$$

$$\text{Cyt} = 20.752$$

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
2 Maintenance of eastern shoulder					
Qty = 703.7 vick				TMB P.No	
				33 to 34 Pm	
		@ RS 58.87		RS =	41075.00
3 Patch repair over bitumen surface with gomm					
Qty = 72.18 m ² vick				TMB P.No	
				35	
4 Main		@ RS 262.45		RS =	18983.00
4 Maintenance of C.R					
Qty = 5 No		vick		TMB P.No	
				35	
		@ RS 1117		RS =	5585.00
5 Maintenance of Road sign					
Qty = 0.26 km vick				TMB P.No	
				35	
		@ RS 1074.51		RS =	277.00
6 Maintenance of 200m post					
Qty = 0.32 km vick				TMB P.No	
				35	
		@ RS 573.96		RS =	184.00
7 Trimming of Grass					
Qty = 8.25 m ² vick				TMB P.No	
				35	
		@ 2.18		RS =	18.00
				RS =	9956.00
	10%	below us her		Aggr (-)	9956.00
				RS =	89604.00

Continuation

 Ravi/M
 30/07/2022
 J.E