

Paid & Cancelled

MEASUREMENT BOOK

SUB-DIVISION

DIVISION

M.B.K
8/11

Lipsey's
M

After
revised

6/26/18

MPASY (SC) Schedule XLV-Form No.-134

3001-18

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	0.5th year	Maint.-rate			
N/Road -	Length of Road from Lockmer. to Mahadevitala Museum Taram in Amravati Block.				
Agency -	Sri Sri Bihari Prasad				
Agreement No -	301 SAD 12017-18				
Actual completion -	12/12/2019				
<u>Wearle Details</u>					
Road has been maintained by Contractor.					
Item(s)	Restoration of Roads Cut				
	etc complete				
10 x 12 x 1.10 x 0.300 =	39.6 m ³				
3 x 8 x 1.20 x 0.500 =	14.4 m ³				
6 x 5.00 x 1.00 x 0.300 =	9 m ³				
3 x 30 x 0.90 x 0.300 =	24.3 m ³				
2 x 15 x 0.80 x 0.300 =	7.2 m ³				
					Total 94.50 m ³
Item(s)	Majut of Shoulder working up Sealing / Shoulder Sealing excess soil - etc course				
	etc				
10 x 30 x 0.750 =	225 m ²				
6 x 30 x 0.700 =	126 m ²				
5 x 20 x 0.800 =	80 m ²				
6 x 10 x 0.700 =	42 m ²				
5 x 15 x 0.750 =	56.2 m ²				
					Total 529.20 m ²

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Item (3) Repair to Aft holes with B79					
— etc complete					
	8 x 3.00 x 1.50 = 36 m ²				
	9 x 2.00 x 1.50 = 27 m ²				
	3 x 3.00 x 2.00 = 18 m ²				
	CB x 1.00 x 1.50 = 0.50 m ²				
	Area = 82.5 m ²				
Total qty	82.50 m ² x 0.075				
	Total Gt 18.63				
	= 0.18 m ³				
Item (4) Patch repair over aft hole					
area — etc complete.					
Qty taken from above Item					
	Area = 82.50 m ²				
	1 unit = 82.50 m ²				
Item (5) Patch repair over B7 surface with 20 mm PVC & seal area					
	3 x 5.00 x 1.50 = 22.50 m ²				
	8 x 2.00 x 1.50 = 24 m ²				
	7 x 3.00 x 1.50 = 31.50 m ²				
	6 x 3.00 x 2.00 = 36 m ²				
	Area = 114 m ²				
Item (6) Maint of 20 units					
	= 0.2 Nip				
Item (7) Maint of 10 units					
	= 0.18 kum				
Item (8) Maint of 200 kum					
	= 0.30 kum				
Item (9) Purchase of goods and ready					
	15 x 0.700 = 10.5 m ²				
	Area = 10.5 m ²				
	Rate = 162.24				
	N.E				

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	<u>Abstract of cost</u>				
Item(01)	Repair of rainouts at wide turn p/m 47				
Mason	0. R. 351.00 fong	15	33.125 ft		
Item(02)	Amount for the shoulder Ref MB ALN (47)				
	529.20 m ² @ Rs 51.52 m ²		Rs 27289/-		
Item(03)	Repair to pit holes with BM 6018 m ³	Ref MB P/H (48)	51.945 f-		
	Rs 8405.95 m ³		Rs 22340/- Rs 4		
Item(04)	Patch repair over pit holes 82.50 m ²	Ref MB (48)	Rs 19281/-		
	Rs 239072 m ²		Rs 22340/-		
Item(05)	Patch repair over BT surface Ref MB (48)				
	114 m ² @ Rs 248.26 /m ²		Rs 28302/-		
Item(06)	Manuf of cinders 2 nos @ Rs 1057.98/ea		Rs 2116/-		
Item(07)	Manuf of rd signs 0.18 km @ Rs 1020.59/km		Rs 183.09/-		
Item(08)	Manuf of 200 kg limestone 0.36 km @ Rs 610.67/km		Rs 183.09/-		
Item(09)	Tiling of garage ss ready 10.50 m ² @ Rs 2.00 /m ²		Rs 21.00/-		
			Total Rs 169994/-		
	1 km of Rd B2B2 @ Rs 160953/-				
Cess	10% Below		Rs 16095/-		
			Rs 144858/-		
	<u>1612124</u>		<u>(P.M.S.)</u> <u>1612124</u>		
	AE		TE		

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	<u>Material Statement</u>				
Bast hawk		172.88 m ³			
Stone metal		6.18 m ³			
Stone chips		4.46 m ³			
Bitumen		738 kg			
Bitumen Emulsion		71.20 kg			
Coarse sand		0.98 m ³			
Pure cement		83.56 kg			
	<u>Total</u>				<u>Revised</u>
		1612124			1612129
		ME			ME